


Index No. T 25

CASS COUNTY LAND CORNER RECORD

T. 139 R. 28 M. 5TH Coordinates: X _____ Y _____
E 1/4 25 Corner common to sections 25 AND 30-139-27



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1863
Original monument Post

Original Evidence Found

Year of search _____ By _____
Monument found _____

	Bearing	Trees		
Species	<u>W. BIRCH</u>	<u>ASPEN</u>	_____	_____
Diameter	<u>12"</u>	<u>10"</u>	_____	_____
Bearing	<u>N39E</u>	<u>N18W</u>	_____	_____
Distance	<u>117 LKS</u>	<u>107 LKS</u>	_____	_____

Original Bearing Trees Found

Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1922 By BEN CLARK
Location filed COUNTY RESURVEY "E-11"
Monument IRON MONUMENT
1919, BEN CLARK, COUNTY BOOK 2 P 316 CORNER IN POND -
NO B.T.S.

Evidence of Subsequent Corner Restoration

Year of search 1937 By CC
Lake Washburn BK # 1 P. 5
Set Acc. 1/4 Cor. 40 CH. from S

Bearing Trees, Reference Objects

Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

Bearing Trees, Reference Objects

_____	_____	_____	_____	_____
_____	_____	_____	_____	_____
_____	_____	_____	_____	_____
_____	_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____

By _____

Filed at _____

Date _____