


Index No. _____

CASS COUNTY LAND CORNER RECORD

T. _____ R. _____ M. _____ Coordinates: X _____ Y _____

Corner common to sections _____



= Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed _____
 Original monument _____

Original Evidence Found

Year of search _____ by _____
 Monument found _____

Bearing Trees

Species _____
 Diameter _____
 Bearing _____
 Distance _____

Original Bearing Trees Found

Species _____
 Diameter _____
 Bearing _____
 Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____
 Location filed:
 Monument:

Evidence of Subsequent Corner Restoration

Year of search _____ By _____
 Location filed:
 Monument:

Bearing Trees, Reference Objects

Species _____
 Diameter _____
 Bearing _____
 Distance _____

Bearing Trees, Reference Objects

Species _____
 Diameter _____
 Bearing _____
 Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____
 Location filed:
 Monument:

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
 Location filed:
 Monument:

Index No. _____

CASS COUNTY LAND CORNER RECORD

T. _____ R. _____ M. _____ Coordinates: X _____ Y _____

Page _____ of _____

Corner common to sections _____


Subsequent Corner Restoration

Evidence of Subsequent Corner Restoration Found

Year surveyed _____ By _____
Location filed:
Monument:

Year of search _____ By _____
Location filed:
Monument:

T. 139 R. 29 M. 5TH Coordinates: X _____ Y _____
NE 21 Corner common to sections 15, 16, 21, 22



EXISTING SURVEYS

Original Government Survey

Year surveyed 1865
Original monument Post

Original Evidence Found

Year of search _____ By _____
Monument found _____

Species	Bearing	Trees	
<u>N. PINE</u>	<u>N. PINE</u>	<u>N. PINE</u>	<u>BL. PINE</u>
Diameter <u>22"</u>	<u>18"</u>	<u>25"</u>	<u>10"</u>
Bearing <u>S 1/2 E</u>	<u>N 47 E</u>	<u>N 89 W</u>	<u>S 75 W</u>
Distance <u>18 LKS</u>	<u>150 LKS</u>	<u>136 LKS</u>	<u>58 LKS</u>

Original Bearing Trees Found

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1975 By Co Hwt Dept.
Location filed Co Rq # 49
Monument 1 1/2" I.P. in place

Evidence of Subsequent Corner Restoration

Year of search 1908 By John Curo
micro film - roll 115 BK 95 P. 37
Find corner set by Hicks

Bearing Trees, Reference Objects

Species	Bearing	Trees	Reference Objects
<u>oak</u>	<u>North</u>	<u>Poplar</u>	<u>Poplar</u>
Diameter <u>6"</u>	<u>6"</u>	<u>12"</u>	
Bearing <u>NW</u>	<u>North</u>	<u>NE</u>	
Distance <u>70.7'</u>	<u>78.4'</u>	<u>81.0'</u>	

Bearing Trees, Reference Objects

Species	Bearing	Trees	Reference Objects
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

CORNER GPS CCSO 8/8/02
CCSO 8/8/02 fd 3/8" Pin, down 0.2
ea &

Certificate - Gary Stevenson - 1987
Doc # 300779
Find 3/8" iron rod w/ RLS cap # 17008 (Land-ckn)
rod set over I.P. and checks with old ties
14" J. Pine N 59 W 113.2' to blize
12" oak N 12 W 70.79'
8" Aspen NORTH 78.37'
12" J. Pine N 47 E 126.35' spk in face
8" Tw. Birch S 40 E 109.20'

AUG. 2000 - CCSO

Find in place; 16d nail, down 0.2'
& CSAH 49 and 50'± west of R/W Signs
N & S of & 49.

REF. TIES:

<u>14" PIN OAK</u>	<u>N 12° W</u>	<u>70.80' (exist. BT.)</u>
<u>5" Pin Oak</u>	<u>N 4° E</u>	<u>64.69'</u>
<u>6" Pin Oak</u>	<u>N 30° E</u>	<u>89.61'</u>
<u>R/W Sign Post</u>	<u>S 32° E</u>	<u>70.23' / NW Cor.</u>