


T. 139 R. 29 M. 5th Coordinates: X _____ Y _____
E 1/4 21 Corner common to sections 21,22



EXISTING SURVEYS

Original Government Survey

Year surveyed 1865
Original monument Post

Original Evidence Found

Year of search _____ by _____
Monument found _____

Bearing Trees

Species	<u>Bl. Pine</u>	<u>Y. Pine</u>	_____
Diameter	<u>8"</u>	<u>20"</u>	_____
Bearing	<u>S 40° E</u>	<u>S 27° W</u>	_____
Distance	<u>20 links</u>	<u>38 links</u>	_____

Original Bearing Trees Found

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 4/1908 By J.W. Curo, LS 1428
Location filed: Curo Book 95, page 44
Monument:
Began at true corner.

Evidence of Subsequent Corner Restoration

Year of search 2/1971 By D. Coulter, LS 5852
Location filed: Plat of SMITH ESTATES, Doc. #201513
Monument:

Bearing Trees, Reference Objects

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Bearing Trees, Reference Objects

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 7/1987 By STEVENSON & ASSOCIATES
Location filed: Curo file 1957
Monument: Found 1.25" I. Pipe,
on fence line. Old pine stump would place corner position
S 20° W, 15.68'
8" Birch, N 20° E, 8.47'
12" Birch, S 65° E, 20.31'

2/2017, C.M. Hidde, LS 44881
Certificate of Survey for Chambers, #8348
Indicates a monument found at corner.

8/2019, J. Kramer, LS 23668
Certificate of Location
Found a 1.25" iron pipe and witnessed as follows.
14" Birch, N 20° E, 8.47'(1987) nail/disc, up 2.0', SE side
Birch snag, S 65° E, 20.31'(1987)
11" Poplar, S 20° E, 10.05' nail/disc, base, SE side
8" Poplar, S 60° W, 25.94' nail/disc, base, SE side
6" Red Oak, N 47° W, 14.56' nail/disc, base, SW side

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
Location filed:
Monument:

