


T. 139 R. 29 M. 5th Coordinates: X _____ Y _____
E 1/4 25 Corner common to sections 25 and 30-139-28



EXISTING SURVEYS

Original Government Survey

Year surveyed 1865
Original monument Post

Original Evidence Found

Year of search _____ by _____
Monument found _____

Bearing Trees

Species	<u>Tamarack</u>	<u>Tamarack</u>	_____
Diameter	<u>12"</u>	<u>12"</u>	_____
Bearing	<u>S 70° E</u>	<u>N 59° W</u>	_____
Distance	<u>15 links</u>	<u>27 links</u>	_____

Original Bearing Trees Found

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 7/1919 By B.F. Clark, LS 231
Location filed: County Book C, page 315
Monument: Iron pipe 2"x 48".
Come in Alder swamp. No witness trees near

Evidence of Subsequent Corner Restoration

Year of search 6/1920 By E.B. Horst, LS 376
Location filed: County Book C, page 348, Curo Book 166, page 8
Monument: Iron pipe

Bearing Trees, Reference Objects

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Bearing Trees, Reference Objects

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 3/1922 By B.F. Clark, LS 231
Location filed: Document #69800
Monument: Iron pipe

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
Location filed: _____
Monument: _____

10/2009, CCHD/SO
#2007.053
Found 2" ODIP, up 1.6' in small grove of large Aspen trees in small swamp and witness as follows:
5" Ash, N 67° W, 29.25'
5" Ash, N 65° E, 32.20'
20" Tamarack, S 60° E, 84.09'

11/2018, D.J. Warner, LS 42656
Certificate of Location
Found 2" ODIP, in swamp and the 2009 witnesses in good condition.

