


Index No. V 23

CASS COUNTY LAND CORNER RECORD

T. 139 R. 31 M. 5TH Coordinates: X _____ Y _____
N 1/4 36 Corner common to sections 25, 36



EXISTING SURVEYS

Original Government Survey
 Year surveyed 1870
 Original monument POST

Bearing Trees

Species	<u>W. OAK</u>	<u>BR. OAK</u>	_____
Diameter	<u>12"</u>	<u>16"</u>	_____
Bearing	<u>S 80 W</u>	<u>N 78 1/2 W</u>	_____
Distance	<u>100 LKS.</u>	<u>120 LKS</u>	_____

Original Evidence Found
 Year of search _____ By _____
 Monument found _____

Original Bearing Trees Found

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration
 Year surveyed _____ By _____
 Location filed _____
 Monument _____

Evidence of Subsequent Corner Restoration
 Year of search _____ By _____

Bearing Trees, Reference Objects

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Bearing Trees, Reference Objects

_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Subsequent Corner Restoration
 Year surveyed _____ By _____
 Location filed _____
 Monument Oct. 1988 w/ Curd # 11395
Sect. of Survey shows monument found

Evidence of Subsequent Corner Restoration Found
 Year of search _____ By _____

Remonumentation certificate prepared _____ By _____
 Filed at _____ Date _____