


Index No. N 9

CASS COUNTY LAND CORNER RECORD

T. 140 R. 25 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
NE 20 Corner common to sections 16, 17, 20, 21



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1867  
Original monument 3" TAM

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Bearing Trees

Species	<u>TAM.</u>	<u>TAM.</u>	<u>TAM.</u>	<u>TAM.</u>
Diameter	<u>3"</u>	<u>3"</u>	<u>3"</u>	<u>3"</u>
Bearing	<u>S65W</u>	<u>N47 1/2 E</u>	<u>S73 1/2 E</u>	<u>N58W</u>
Distance	<u>15 LKS.</u>	<u>24 LKS</u>	<u>36 LKS</u>	<u>50 LKS</u>

Original Bearing Trees Found

Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1937 By CCC  
Location filed Washburn Lake - BK# 4 P. 39  
Monument at 5280' from E. - set APPROX SEC. COR.  
BK. 4 P. 40 - at 5168' from W. APPROX COR IS  
100' North.

Evidence of Subsequent Corner Restoration

Year of search 1911 By M. Watson  
Twp. Road order, Surveyors Report  
indicates road on N-S Section  
line.

Bearing Trees, Reference Objects

Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

Bearing Trees, Reference Objects

Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_

Remonumentation certificate prepared \_\_\_\_\_  
Filed at \_\_\_\_\_

By \_\_\_\_\_  
Date \_\_\_\_\_