


Index No. R 21

CASS COUNTY LAND CORNER RECORD

T. 140 R. 26 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
NE 26 Corner common to sections 23, 24, 25, 26



O = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1871  
Original monument POST

	Bearing	Trees	
Species	<u>BIRCH</u>	<u>BIRCH</u>	<u>TAM</u>
Diameter	<u>7"</u>	<u>8"</u>	<u>6"</u>
Bearing	<u>S 8 W</u>	<u>N 40 E</u>	<u>S 42 E</u>
Distance	<u>36 lks</u>	<u>52 lks</u>	<u>65 lks</u>

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Original Bearing Trees Found

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1920 By BEN CLARK  
Location filed COUNTY BOOK "C" P. 37  
Monument FIND GOUT BIT: 6" TAM S 42 E 13 LKS SET  
3x48" OAK POST

Evidence of Subsequent Corner Restoration

Year of search 1937 By CCC  
Washburn Lake - BK # 1 P. 37  
Find 2" 1/4" w/ cap 23/24  
26/25  
81.24 CH - from west

Bearing Trees, Reference Objects

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Bearing Trees, Reference Objects

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_

Remonumentation certificate prepared \_\_\_\_\_ By \_\_\_\_\_  
Filed at \_\_\_\_\_ Date \_\_\_\_\_