


Index No. N 13

CASS COUNTY LAND CORNER RECORD

T. 140 R. 28 M. 5TH Coordinates: X _____ Y _____
NE 21 Corner common to sections 15, 16, 21, 22



EXISTING SURVEYS

Original Government Survey
 Year surveyed 1870
 Original monument Post

Bearing Trees			
Species	W. Birch	W. BIRCH	W. PINE
Diameter	<u>6"</u>	<u>7"</u>	<u>9"</u>
Bearing	<u>S57W</u>	<u>N55E</u>	<u>N42W</u>
Distance	<u>80 LKS</u>	<u>40 LKS</u>	<u>50 LKS</u>

Original Evidence Found
 Year of search _____ By _____
 Monument found _____

Original Bearing Trees Found

Species	Diameter	Bearing	Distance

Subsequent Corner Restoration
 Year surveyed 1920 By BEN CLARK
 Location filed COUNTY BOOK "C" P. 560
 Monument FND I.M.
1920, BEN CLARK, BOOK "D" P. 187 FND WOOD POST AND
NEW B.T.: 12" N. PINE S51 60.6' SET 3x30" I.P.

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance

Evidence of Subsequent Corner Restoration
 Year of search 1941 By CCC
Washburn Lake - BK #14 P. 18
at 5280' from South - set approx Cor 3" Aspen
1965 - Co. Hwt Dept - Co. R0# 54
Found 2" capped I.P.

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance

Subsequent Corner Restoration
 Year surveyed Nov 1998 By CC Land Dept - J.L.A.R.
 Location filed _____
 Monument Exc condition

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance

Evidence of Subsequent Corner Restoration Found
 Year of search DEC 2002 By CCSO
Found 2" ODIP w/plumber cap, up 0.9,
on top of ridge. 115' North of bog.
 * 6" Maple N 44° W 60.97' up 10" W side
 * 6" Balsam N 64° E 76.99' up 10" N side
 * 19" N. Pine S 58° W 60.52' up 10" S side
 * Dist. to dbl hd nail.

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance

Remonumentation certificate prepared _____ By _____
Filed at _____ Date _____