


Index No. V5

CASS COUNTY LAND CORNER RECORD

T. 140 R. 28 M. 5TH Coordinates: X _____ Y _____
NE 31 Corner common to sections 29, 30, 31, 32



○ = Corner

EXISTING SURVEYS

Original Government Survey
 Year surveyed 1870
 Original monument POST

Original Evidence Found
 Year of search _____ By _____
 Monument found _____

Bearing Trees
 Species DRY PINE DRY PINE DRY PINE
 Diameter 26" 24" 24"
 Bearing S85E N50E S68W
 Distance 26 LKS 16 LKS 28 LKS

Original Bearing Trees Found
 Species _____
 Diameter _____
 Bearing _____
 Distance _____

Subsequent Corner Restoration
 Year surveyed 1941 By CCC
 Location filed Washburn Lake - BK# 14 P. 26
 Monument at 5280' from South - set APPROX cor 3' Arch

Evidence of Subsequent Corner Restoration
 Year of search 10/3/1998 By LANDECKER & ASSOC.
INDICATES THAT A 1" IRON PIPE IS IN PLACE, UP 0.7' AND THAT THE POSITION WAS LOCATED VIA GPS

Bearing Trees, Reference Objects
 Species _____
 Diameter _____
 Bearing _____
 Distance _____

Bearing Trees, Reference Objects
OAK OAK ASPEN
10" TWIN 22" 20"
N41°W N85°E S44°E
33.35 37.10 19.15

V-5

Subsequent Corner Restoration
 Year surveyed _____ By _____
 Location filed _____
 Monument _____

Evidence of Subsequent Corner Restoration Found
 Year of search _____ By _____

Remonumentation certificate prepared _____ By _____
 Filed at _____ Date _____