


Index No. A-B 13

CASS COUNTY LAND CORNER RECORD

T. 140 R. 29 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
M.C.# 74 Corner common to sections 3, 4



EXISTING SURVEYS

Original Government Survey

Year surveyed 1870  
Original monument POST

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Bearing Trees  
Species J. Pine N. Pine \_\_\_\_\_  
Diameter 4" 5" \_\_\_\_\_  
Bearing N78E N38W \_\_\_\_\_  
Distance 25 lks 20 lks. \_\_\_\_\_

Original Bearing Trees Found

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration

Year of search \_\_\_\_\_ By \_\_\_\_\_

Bearing Trees, Reference Objects

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Bearing Trees, Reference Objects

\_\_\_\_\_

Subsequent Corner Restoration

Year surveyed 1966 By R.F. Schneider  
Location filed \_\_\_\_\_  
Monument Found 3/4" pipe in rock mound  
Tie: 8" Cedar S10W 2.35'

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
PLAT - FOURTH ADDITION TO PINE SHORE ESTATES  
R.F. SCHNEIDER 1971 IRON-NOT LABELED M.C.

Remonumentation certificate prepared \_\_\_\_\_  
Filed at \_\_\_\_\_

By \_\_\_\_\_  
Date \_\_\_\_\_