


Index No. A 15

CASS COUNTY LAND CORNER RECORD

T. 141 R. 27 M. 5TH Coordinates: X _____ Y _____
N 14 3 Corner common to sections 3 AND 34-142-27



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1873
Original monument POST

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees

Species	<u>BL. OAK</u>	<u>N. PINE</u>	_____	_____
Diameter	<u>6"</u>	<u>12"</u>	_____	_____
Bearing	<u>S70W</u>	<u>N40W</u>	_____	_____
Distance	<u>8 LKS</u>	<u>35 LKS</u>	_____	_____

Original Bearing Trees Found

Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Bearing Trees, Reference Objects

_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
CERTIFICATE - BILL OKERMAN - 1969
Found wood post in poor condition. W. Pine
14" S49W 58.1' now 26"; W. Pine 18" S40E
14.7' now 24". Set 2"x5' galvanized
steel pipe filled with concrete and capped
with 3" stamped brass tablet. Ties: 22"
Norway Pine S33E 66.9'; 21" Norway
Pine S30W 102.7'; 21" Norway Pine
S72W 44.9'.

Remonumentation certificate prepared _____

By _____

Filed at _____

Date _____