


Index No. H-J2

CASS COUNTY LAND CORNER RECORD

T. 141 R. 27 M. 5th Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_

SMC @ N Corner common to sections 7  
W 1/4 LINE (WHERE IT INTERSECTS ORIG. MEANDER LINE)



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1919  
 Original monument 1x36" I.P. W/BRASS CAP  
 Bearing Trees 1919

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
 Monument found \_\_\_\_\_

Species W. OAK HARD MAPLE  
 Diameter 20" 18"  
 Bearing N17°2'E N86°E  
 Distance 55 LKS 26 LKS

Original Bearing Trees Found

Species \_\_\_\_\_  
 Diameter \_\_\_\_\_  
 Bearing \_\_\_\_\_  
 Distance \_\_\_\_\_

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
 Location filed \_\_\_\_\_  
 Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration

Year of search \_\_\_\_\_ By \_\_\_\_\_

Bearing Trees, Reference Objects

Species \_\_\_\_\_  
 Diameter \_\_\_\_\_  
 Bearing \_\_\_\_\_  
 Distance \_\_\_\_\_

Bearing Trees, Reference Objects

Species \_\_\_\_\_  
 Diameter \_\_\_\_\_  
 Bearing \_\_\_\_\_  
 Distance \_\_\_\_\_

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
 Location filed \_\_\_\_\_  
 Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_

Remonumentation certificate prepared \_\_\_\_\_

By \_\_\_\_\_

Filed at \_\_\_\_\_

Date \_\_\_\_\_