Index No. Q 7

# CASS COUNTY LAND CORNER RECORD

T. 141 R. 27 M. 5TH Coordinates: X _____ Y _____

C.S. 1/16 Corner common to sections 20




O = Corner

## EXISTING SURVEYS

### Original Government Survey

Year surveyed 1919

Original monument 1x36" I.P. W/ BRASS CAP. S1/16 C | S20 C 1979

### Original Evidence Found

Year of search _____ By _____

Monument found _____

### Bearing Trees

| | | | | |
|---|---|---|---|---|
| Species | CEDAR | CEDAR | | |
| Diameter | 8" | 15" | | |
| Bearing | N68W | S26-45W | | |
| Distance | 24 LKS | 42 LKS | | |

### Original Bearing Trees Found

| | | | | |
|---|---|---|---|---|
| Species | | | | |
| Diameter | | | | |
| Bearing | | | | |
| Distance | | | | |

### Subsequent Corner Restoration

Year surveyed 1982 By Gary Stevenson

Location filed Corner Certificate

Monument In 1980 USFS End brass cap. and 10" dead cedar NW and cedar S27W

### Bearing Trees, Reference Objects

| | | | | |
|---|---|---|---|---|
| Species | Ash | Cedar | Cedar | |
| Diameter | 9" | 7" | 13" | |
| Bearing | N6E | S66E | S37E | |
| Distance | 15.9' | 32.9' | 25.3' | |

### Evidence of Subsequent Corner Restoration

Year of search _____ By _____

### Bearing Trees, Reference Objects

| | | | |
|---|---|---|---|
| | | | |
| | | | |
| | | | |
| | | | |

### Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed _____

Monument _____

### Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Certificate - Gary Stevenson - filed by USFS

Doc # 279343 1984 - dated - 1982

Remonumentation certificate prepared _____ By _____

Filed at _____ Date _____