


Index No. 623

CASS COUNTY LAND CORNER RECORD

T. 141 R. 28 M. 5th Coordinates: X _____ Y _____
C14 Corner common to sections 12



O = Corner

EXISTING SURVEYS

Original Government Survey

Original Evidence Found

Year surveyed 1918
Original monument 1x 36" I.P. w/ BRASS CAP. C14 512 1918

Year of search _____ By _____
Monument found _____

Bearing Trees	
Species <u>BIRCH</u>	<u>N. PINE</u>
Diameter <u>6"</u>	<u>14"</u>
Bearing <u>N45 1/4 E</u>	<u>N47 1/4 W</u>
Distance <u>173 LKS</u>	<u>120 LKS</u>

Original Bearing Trees Found		
Species _____	_____	_____
Diameter _____	_____	_____
Bearing _____	_____	_____
Distance _____	_____	_____

Subsequent Corner Restoration

Evidence of Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Year of search 1973 By William Okerman
Found GLO monument in good condition.

Bearing Trees, Reference Objects

Bearing Trees, Reference Objects

Species _____	_____	_____
Diameter _____	_____	_____
Bearing _____	_____	_____
Distance _____	_____	_____

<u>W. OAK</u>	<u>W. OAK</u>	<u>N. PINE</u>
<u>7"</u>	<u>7"</u>	<u>22"</u>
<u>S84 W</u>	<u>N 29 W</u>	<u>N 47 W</u>
<u>34.30'</u>	<u>48.30'</u>	<u>95.70'</u>

Subsequent Corner Restoration

Evidence of Subsequent Corner Restoration Found

Year surveyed _____ By _____
Location filed _____
Monument _____

Year of search _____ By _____
CERTIFICATE - BILL OKERMAN - 1973

Remonumentation certificate prepared _____ By _____
Filed at _____ Date _____