


Index No. 67

CASS COUNTY LAND CORNER RECORD

T. 141 R. 28 M. 5th Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
C114 Corner common to sections 8



EXISTING SURVEYS

Original Government Survey

Year surveyed 1918  
Original monument 1x36' 1/2 w/BRASS C114 SB  
CAP 1918

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Bearing Trees  
Species J. ANE W. ANE \_\_\_\_\_  
Diameter 10" 7" \_\_\_\_\_  
Bearing S76E N24 1/2 W \_\_\_\_\_  
Distance 90 LKS 87 LKS \_\_\_\_\_

Original Bearing Trees Found

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

O = Corner

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration

Year of search 1971 By William Okerman  
Found GLO monument in good condition

Bearing Trees, Reference Objects

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Bearing Trees, Reference Objects

Oak Oak Red Pine  
13" 8" 17"  
N54W S33W S29E  
46.1' 44.4' 84.8'

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
CERTIFICATE - BILL OKERMAN - 1971  
Nov 2001 R. Mustonen # 11946  
Cert. of Surv. shows Mon. Found

Remonumentation certificate prepared \_\_\_\_\_ By \_\_\_\_\_

Filed at \_\_\_\_\_ Date \_\_\_\_\_