


Index No. 218

CASS COUNTY LAND CORNER RECORD

T. 141 R. 20 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
C.W. 116 Corner common to sections 14



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1918  
Original monument 1x36" I.P. w/ BRASS CAP w 116 C 514 C 1918

Bearing Trees

Species	<u>N. PINE</u>	<u>N. PINE</u>	_____	_____
Diameter	<u>8"</u>	<u>18"</u>	_____	_____
Bearing	<u>N 74 1/2 E</u>	<u>N 35 1/2 W</u>	_____	_____
Distance	<u>193 LKS</u>	<u>93 LKS</u>	_____	_____

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Original Bearing Trees Found

Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Bearing Trees, Reference Objects

Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

Evidence of Subsequent Corner Restoration

Year of search 1971 By William Okerman  
Found GLO monument in good condition

Bearing Trees, Reference Objects

<u>W. Oak</u>	<u>R. Oak</u>	<u>W. Oak</u>	_____	_____
<u>6"</u>	<u>8"</u>	<u>6"</u>	_____	_____
<u>N 32 E</u>	<u>S 74 E</u>	<u>S 1 E</u>	_____	_____
<u>42.40'</u>	<u>20.00'</u>	<u>18.00'</u>	_____	_____

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
CERTIFICATE - BILL OKERMAN - 1971

Remonumentation certificate prepared \_\_\_\_\_ By \_\_\_\_\_

Filed at \_\_\_\_\_ Date \_\_\_\_\_