


Index No. L 5-6

CASS COUNTY LAND CORNER RECORD

T. 141 R. 28 M. 5TH Coordinates: X _____ Y _____

SMC ON Corner common to sections _____
E-W 1/4 LINE



EXISTING SURVEYS

Original Government Survey
 Year surveyed 1918
 Original monument 1x36" i.p. witness SMC 517 C
CAP 1918 517

Original Evidence Found
 Year of search _____ By _____
 Monument found _____

Bearing Trees
 Species POPLAR POPLAR
 Diameter 6" 8"
 Bearing N18 3/4 E S49 1/4 E
 Distance 115 LKS 68 LKS

Original Bearing Trees Found
 Species _____
 Diameter _____
 Bearing _____
 Distance _____

Subsequent Corner Restoration
 Year surveyed _____ By _____
 Location filed _____
 Monument _____

Evidence of Subsequent Corner Restoration
 Year of search 1972 By William Okerman
Found GLO monument in good condition.

Bearing Trees, Reference Objects
 Species _____
 Diameter _____
 Bearing _____
 Distance _____

Bearing Trees, Reference Objects
OAK OAK
8" 8"
S 86 E S 30 E
31.00' 94.00'

Subsequent Corner Restoration
 Year surveyed _____ By _____
 Location filed _____
 Monument _____

Evidence of Subsequent Corner Restoration Found
 Year of search _____ By _____
CERTIFICATE - BILL OKERMAN - 1972

Remuneration certificate prepared _____ By _____
 Filed at _____ Date _____