

T. 141 R. 28 M. 5th Coordinates: X _____ Y _____

MC #13 Corner common to sections 15, 22



22

● = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1874
Original monument Post

Original Evidence Found

Year of search _____ by _____
Monument found _____

Bearing Trees

Species Oak
Diameter 10"
Bearing N 65° W
Distance 73 links

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed 9/1918 By E.G. Harrington, GLO
Location filed: Minnesota Historical Society, notes 70 T141N
Monument: Set 1"x 36" iron pipe with brass cap at proportional position, unable to find any evidence of original post or bearing trees, the following accessories were noted
S15
S22
R28W
1918

Evidence of Subsequent Corner Restoration

Year of search 8/1952 By W.J. Spain, LS 2003
Location filed: Spain Book 1949, page 104 and 105
Monument: Found USGLO monument locate M.C. USGLO and run W., fail to find 1/16 corner.

Bearing Trees, Reference Objects

Species Poplar Poplar
Diameter 10" 10"
Bearing S 31 1/4° W N 84 1/2° W
Distance 105 links 91 links

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed 9/1958 By G.G. Holmstrom, LS 1861
Location filed: Plat of MAPLE LAKE GROVE, Doc. #160016
Monument: U.S. Meander Corner in place


Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
Location filed: _____
Monument: _____

Index No. N 16-17

CASS COUNTY LAND CORNER RECORD

T. 141 R. 28 M. 5TH Coordinates: X _____ Y _____
M.C. # 13 Corner common to sections 15, 22



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1874
Original monument Post

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees

Species OAK
Diameter 10"
Bearing N65W
Distance 73 LKS

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed 1918 By GLO
Location filed SECRETARY OF STATE
Monument PROPORTIONAL POSITION - NO ORIG. EVIDENCE
SET 1X36" I.P. W/ BRASS CAP T. 141 N

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects ^{515/mc}
_{522/1918}

Species POPLAR POPLAR
Diameter 10" 10"
Bearing S 31 1/4 W N 84 1/2 W
Distance 105 LKS 91 LKS

Bearing Trees, Reference Objects

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
PLAT - MAPLE LAKE GROVE
Gus Holmstrom 1958

Remonumentation certificate prepared _____ By _____
Filed at _____ Date _____