


Index No. R2-3

CASS COUNTY LAND CORNER RECORD

T. 141 R. 28 M. 5TH Coordinates: X _____ Y _____
E-W 1/64 Corner common to sections 19, 30



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1918
 Original monument 1x36" 1 1/2" W/ 5000'S
CAP
 Bearing Trees
 Species _____
 Diameter _____
 Bearing _____
 Distance _____

519
API
TR
1401
530
1918

Original Evidence Found

Year of search _____ By _____
 Monument found _____

Original Bearing Trees Found

Species _____
 Diameter _____
 Bearing _____
 Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____
 Location filed _____
 Monument _____

Bearing Trees, Reference Objects

Species _____
 Diameter _____
 Bearing _____
 Distance _____

Evidence of Subsequent Corner Restoration

Year of search 1973 By William Okerman
Found GLO monument in good condition.

Bearing Trees, Reference Objects

<u>W. OAK</u>	<u>Birch</u>	<u>W. OAK</u>
<u>8"</u>	<u>10"</u>	<u>11"</u>
<u>N43 E</u>	<u>N22 W</u>	<u>N60 W</u>
<u>23.10'</u>	<u>39.50'</u>	<u>50.80'</u>

Subsequent Corner Restoration

Year surveyed _____ By _____
 Location filed _____
 Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
CERTIFICATE - BILL OKERMAN - 1973

Remonumentation certificate prepared _____

By _____

Filed at _____

Date _____