


Index No. E 6

CASS COUNTY LAND CORNER RECORD

T. 141 R. 29 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
W. 116 Corner common to sections 5, 8



EXISTING SURVEYS

Original Government Survey

Year surveyed 1918  
Original monument 1x36" I.P.W./BRASS CAP W. 116 55  
58  
1910

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Bearing Trees  
Species ROAK BL. OAK \_\_\_\_\_  
Diameter 10" 8" \_\_\_\_\_  
Bearing N46E S75-15W \_\_\_\_\_  
Distance 30 LKS 39 LKS \_\_\_\_\_

Original Bearing Trees Found

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Subsequent Corner Restoration

Year surveyed OCT 2003 By T. Freeman #21367  
Location filed \_\_\_\_\_  
Monument Cert. of sur. shows mon. found

Evidence of Subsequent Corner Restoration

Year of search \_\_\_\_\_ By \_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

Bearing Trees, Reference Objects

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Bearing Trees, Reference Objects

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
CERTIFICATE - BUTLER SMITH - HWY ENGINEER - 1921  
Found iron pipe with brass cap. TIES:  
18" Poplar N 35° 15' E 41.5'; 30" Poplar N 41°  
45' W 43.8'.

MAR 2002 T. FREEMAN  
CERT OF SUR SHOWS MON FOUND

Remonumentation certificate prepared \_\_\_\_\_

By \_\_\_\_\_

Filed at \_\_\_\_\_

Date \_\_\_\_\_