


Index No. V 3

CASS COUNTY LAND CORNER RECORD

T. 141 R. 29 M. 5TH Coordinates: X _____ Y _____
N 1/4 31 Corner common to sections 30, 31



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1873
Original monument POST

Original Evidence Found

Year of search _____ By _____
Monument found _____

Species	Bearing	Trees
<u>BIRCH</u>	<u>B. OAK</u>	
<u>5"</u>	<u>6"</u>	
<u>N 33 E</u>	<u>S 79 E</u>	
<u>56 LKS</u>	<u>62 LKS</u>	

Original Bearing Trees Found

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1989 By David Landecker
Location filed _____
Monument Set 2" x 54" iron pipe with brass cap and plastic base with magnet.

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Species	Bearing	Trees	Reference Objects
<u>Birch</u>	<u>N. Pine</u>	<u>N. Pine</u>	
<u>11"</u>	<u>26"</u>	<u>19"</u>	
<u>N 52 W</u>	<u>S 75 E</u>	<u>S 6 W</u>	
<u>61.08'</u>	<u>87.99'</u>	<u>89.76'</u>	

Bearing Trees, Reference Objects

_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
1989 Certificate - David Landecker
Doc. # 311852

Re-monumentation certificate prepared _____

By _____

Filed at _____

Date _____