


T. 141 R. 30 M. 5th Coordinates: X _____ Y _____

CN 1/16 Corner common to sections 4



EXISTING SURVEYS

Original Government Survey

Year surveyed 1917
Original monument 1"x 36" Brass cap iron pipe

Original Evidence Found

Year of search _____ by _____
Monument found _____

Bearing Trees

Species	<u>J. Pine</u>	<u>R. Oak</u>
Diameter	<u>10"</u>	<u>8"</u>
Bearing	<u>S 64 3/4° E</u>	<u>S 68 1/4° W</u>
Distance	<u>292 links</u>	<u>80 links</u>

Original Bearing Trees Found

Species	_____	_____
Diameter	_____	_____
Bearing	_____	_____
Distance	_____	_____

Subsequent Corner Restoration

Year surveyed 2/1963 By R.H. McDonald (USFS)
Location filed: USFS Book 2, page 65
Monument: Found brass cap monument, under fence line.
An Affidavit as to Location of Government corner was filed by P. Meyer, LS 3628 on this information. No Document Number.

Evidence of Subsequent Corner Restoration

Year of search 1981 By W.A. (USFS)
Location filed: Unknown
Monument: Found GLO brass cap

Bearing Trees, Reference Objects

Species	<u>R. Pine(1917)</u>	<u>J. Pine</u>	<u>J. Pine</u>
Diameter	<u>16"</u>	<u>12"</u>	<u>13"</u>
Bearing	<u>S 64°45' E</u>	<u>N 7° W</u>	<u>N 33° E</u>
Distance	<u>192.7'</u>	<u>12.45'</u>	<u>9.4'</u>

Bearing Trees, Reference Objects

Species	<u>W. Oak</u>	<u>Steel Sign</u>
Diameter	<u>8"</u>	<u>Post</u>
Bearing	<u>S 12° E</u>	<u>East</u>
Distance	<u>35.25'</u>	<u>4.0'</u>

Subsequent Corner Restoration

Year surveyed 2/1985 By T. Freeman & Hammitzsch
Location filed: CCHD/SO
Monument: Found GLO brass cap and the 1963 and 1981 USFS witnesses.

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
Location filed: _____
Monument: _____


3/2012, CCHD/SO
#2012.005
Found GLO Brass cap, up 1.0', SE of small pond, the 1917 Red Pine standing green in clear cut, 1963 Jack Pine are snags, 1981 witnesses are good, add the following:
10" Burr Oak, N 42° E, 22.58'

3/2013, P.A. Trottier, LS 41002
Certificate of Location
Found GLO Brass cap, up 1.0' and witnesses as follows.
14" Jack Pine, N 7° W, 12.45' nail
6" Oak, S 88° E, 22.13' nail
16" Oak, S 12° E, 35.25' nail

Index No. B11

CASS COUNTY LAND CORNER RECORD

T. 141 R. 30 M. 5TH Coordinates: X _____ Y _____
C. N. 116 Corner common to sections 4



EXISTING SURVEYS

Original Government Survey

Year surveyed 1917

Original monument 1x36" 11P.W/BRASS N116^C 54
CAP 1917

Bearing Trees

Species	<u>J. Pine</u>	<u>R. Oak</u>	
Diameter	<u>10"</u>	<u>8"</u>	
Bearing	<u>S64³4E</u>	<u>S68¹4W</u>	
Distance	<u>292 LKS</u>	<u>80 LKS</u>	

Original Evidence Found

Year of search _____ By _____

Monument found _____

Original Bearing Trees Found

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1985 Feb 28 By Freeman - Kunitzsch

Location filed _____

Monument Find brass cap monument

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Species	<u>J. Pine</u>	<u>J. Pine</u>	<u>W. oak</u>
Diameter	<u>15"</u>	<u>14"</u>	<u>8"</u>
Bearing	<u>N7W</u>	<u>N33E</u>	<u>S12E</u>
Distance	<u>12.45'</u>	<u>9.4'</u>	<u>35.25'</u>

Bearing Trees, Reference Objects

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed _____

Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

CERTIFICATE - PETE MEYER - 1963

15" J. Pine N7W 12.45

14" J. Pine N33E 9.4

8" W. oak S12E 35.25'

Found GLO monument in good condition.

Remonumentation certificate prepared _____ By _____

Filed at _____ Date _____