


Index No. C11

CASS COUNTY LAND CORNER RECORD

T. 141 R. 30 M. 5TH Coordinates: X _____ Y _____
C114 Corner common to sections 4



EXISTING SURVEYS

Original Government Survey

Year surveyed 1917
Original monument 1x36" IR. W/BRASS CAP C114 54 1917

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees
Species POPULAR POPULAR
Diameter 10" 8"
Bearing N10W N89W
Distance 54 LKS 233 LKS

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed 1963 By PETE MEYER
Location filed _____
Monument Found GLO monument in good condition.

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Species J. Pine
Diameter 16"
Bearing S36E
Distance 125.40'

Bearing Trees, Reference Objects

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
CERTIFICATE - PETE MEYER - 1963

Remonumentation certificate prepared _____

By _____

Filed at _____

Date _____