


Index No. E-F 16

CASS COUNTY LAND CORNER RECORD

T. 141 R. 30 M. 5TH Coordinates: X _____ Y _____

NE 1/4 Corner common to sections 10
AP# 1 1644, AP# 7 1284



EXISTING SURVEYS

Original Government Survey

Year surveyed 1917 TR 1284 AP 7 TR 1388
 Original monument N36° 1/2 P.W. BRASS AP 1
CAP TR 1644

Original Evidence Found

Year of search _____ By _____
 Monument found _____

Bearing Trees

Species _____ S/O
 Diameter _____ 1917
 Bearing _____
 Distance _____

Original Bearing Trees Found

Species _____
 Diameter _____
 Bearing _____
 Distance _____

O = Corner

Subsequent Corner Restoration

Year surveyed 1968 By William Okerman
 Location filed _____
 Monument Found GLO monument in good condition.

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Species	<u>R. Oak</u>	<u>R. Oak</u>	<u>R. Oak</u>	<u>Cedar Post</u>
Diameter	<u>8"</u>	<u>9"</u>	<u>6"</u>	<u>4"x4"x72"</u>
Bearing	<u>N42 E</u>	<u>S14 W</u>	<u>N83 W</u>	<u>West</u>
Distance	<u>16.12'</u>	<u>14.01'</u>	<u>12.70'</u>	<u>5.3'</u>

Bearing Trees, Reference Objects

Subsequent Corner Restoration

Year surveyed _____ By _____
 Location filed _____
 Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
CERTIFICATE - BILL OKERMAN - 1968

Remonumentation certificate prepared _____

By _____

Filed at _____

Date _____