


Index No. 27

CASS COUNTY LAND CORNER RECORD

T. 141 R. 30 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
S1/4 32 Corner common to sections 32



EXISTING SURVEYS

Original Government Survey

Year surveyed 1863  
Original monument POST

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Species		Bearing		Trees	
<u>SUGAR</u>	<u>SUGAR</u>	<u>8"</u>	<u>6"</u>		
<u>8"</u>	<u>6"</u>	<u>N41W</u>	<u>N8E</u>		
<u>42 LKS</u>	<u>75 LKS</u>				

Original Bearing Trees Found	
Species _____	_____
Diameter _____	_____
Bearing _____	_____
Distance _____	_____

Subsequent Corner Restoration

Year surveyed 1989 By David Landecker  
Location filed \_\_\_\_\_  
Monument Set 2" x 48" iron pipe with brass cap and plastic base with magnet.

Evidence of Subsequent Corner Restoration

Year of search \_\_\_\_\_ By \_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

Bearing Trees, Reference Objects

Species	Bearing	Trees	Reference Objects
<u>R. Oak</u>	<u>R. Oak</u>	<u>R. Oak</u>	
<u>12"</u>	<u>10"</u>	<u>13"</u>	
<u>N82W</u>	<u>N3W</u>	<u>N40E</u>	
<u>27.35'</u>	<u>7.18'</u>	<u>37.95'</u>	

Bearing Trees, Reference Objects

_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
1989 Certificate - David Landecker  
Doc. # 311259

Remonumentation certificate prepared \_\_\_\_\_ By \_\_\_\_\_  
Filed at \_\_\_\_\_ Date \_\_\_\_\_