


Index No. S-T 21

CASS COUNTY LAND CORNER RECORD

T. 142 R. 26 M. 5TH Coordinates: X _____ Y _____
M.C. # 3 Corner common to sections 25, 26



EXISTING SURVEYS

Original Government Survey

Year surveyed 1872
Original monument POST

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees

Species	<u>TAM.</u>	<u>TAM.</u>	_____	_____
Diameter	<u>4"</u>	<u>4"</u>	_____	_____
Bearing	<u>N45W</u>	<u>S40E</u>	_____	_____
Distance	<u>5 LKS</u>	<u>5 LKS</u>	_____	_____

Original Bearing Trees Found

Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1921 By JAMES FLYNN
Location filed COUNTY BOOK 2 P 415
Monument FIND OLD GOVT BIT: TAM STUMP 5' N45W
3.3' 1 1/2 x 44" IRON MONUMENT
COUNTY RESURVEY 1921 "E-2"

Evidence of Subsequent Corner Restoration

Year of search 1914 By GZO
FIND BOTH OLD BITS. SET 4x48" CEDAR POST
SET A.M.C. ON ISLAND 14.65 CH. N. OF M.C.
SET 12x9x6" GRANITE STONE 1 BT; 12" SPRUCE N87E
1145

Bearing Trees, Reference Objects

Species	<u>TAM</u>	_____	_____	_____
Diameter	<u>5"</u>	_____	_____	_____
Bearing	<u>N58W</u>	_____	_____	_____
Distance	<u>49'</u>	_____	_____	_____

Bearing Trees, Reference Objects

_____	_____	_____	_____	_____
_____	_____	_____	_____	_____
_____	_____	_____	_____	_____
_____	_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____

By _____

Filed at _____

Date _____