


Index No. N-05

CASS COUNTY LAND CORNER RECORD

T. 142 R. 27 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
MC # 27 Corner common to sections 19, 20



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1873  
Original monument Post

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

	Bearing Trees	
Species	<u>W. PINE</u>	<u>FIR</u>
Diameter	<u>7"</u>	<u>6"</u>
Bearing	<u>S58E</u>	<u>N23W</u>
Distance	<u>20 LKS</u>	<u>36 LKS</u>

Original Bearing Trees Found

Species	_____	_____
Diameter	_____	_____
Bearing	_____	_____
Distance	_____	_____

Subsequent Corner Restoration

Year surveyed 1919 By GLD  
Location filed SEC. OF STATE  
Monument NO ORIG. EVIDENCE - SET 1x36" I.P.W/BARS  
CAP. T142N/R27W  
519 | 520  
MC  
1919

Evidence of Subsequent Corner Restoration

Year of search \_\_\_\_\_ By \_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

Bearing Trees, Reference Objects

Species	<u>BALSAM</u>	<u>BIRCH</u>
Diameter	<u>6"</u>	<u>6"</u>
Bearing	<u>N26E</u>	<u>N51W</u>
Distance	<u>41 LKS</u>	<u>28 LKS</u>

Bearing Trees, Reference Objects

_____	_____	_____
_____	_____	_____
_____	_____	_____
_____	_____	_____

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_

Remonumentation certificate prepared \_\_\_\_\_

By \_\_\_\_\_

Filed at \_\_\_\_\_

Date \_\_\_\_\_