


Index No. V 17

CASS COUNTY LAND CORNER RECORD

T. 142 R. 27 M. 5TH Coordinates: X _____ Y _____
NE 34 Corner common to sections 26, 27, 34, 35 W.C. 6.97 CH. WEST



EXISTING SURVEYS

Original Government Survey

Year surveyed 1873

Original monument POST NO B.T.S.
W.C. POST 6.97 CH. WEST

B.T. TO W.C.

Species	Bearing	Trees
<u>TAM.</u>	<u>5'</u>	<u>CEDR</u>
<u>DIAMETER</u>	<u>N 42'</u>	<u>6"</u>
<u>BEARING</u>	<u>?</u>	<u>SIDE</u>
<u>DISTANCE</u>	<u>6 LKS</u>	

Original Evidence Found

Year of search _____ By _____

Monument found _____

Original Bearing Trees Found

Species	Bearing	Trees
_____	_____	_____
<u>DIAMETER</u>	_____	_____
<u>BEARING</u>	_____	_____
<u>DISTANCE</u>	_____	_____

O = Corner

Subsequent Corner Restoration

Year surveyed 1981 By GARY STEVENSON

Location filed PLAT OF SURVEY "E-74"

Monument SET COUNTY EAST IRON MONUMENT FROM
1972 COUNTY SURVEY RECORD.

Evidence of Subsequent Corner Restoration

Year of search 1922 By J. H. FLYNN

COUNTY BOOK "D" P. 108 - FND 6" X 6" X 6" CEDAR POST HE
SET IN 1915

Bearing Trees, Reference Objects

Species	Bearing	Reference Objects
<u>NAIL & DISC N. END</u>	<u>NE</u>	<u>NAIL & DISC</u>
<u>DIAMETER</u>	<u>89.21'</u>	<u>S. END CMP</u>
<u>BEARING</u>	<u>88.72'</u>	<u>SE</u>
<u>DISTANCE</u>		

Bearing Trees, Reference Objects

Species	Bearing	Reference Objects
_____	_____	_____
_____	_____	_____
_____	_____	_____
_____	_____	_____

V-17

Subsequent Corner Restoration

Year surveyed 1999 By CCSO

Location filed #99046

Monument Found & Located 1981 C.I.M.

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

CERTIFICATE - GARY STEVENSON - 1981
DOC. # 260597

Remonumentation certificate prepared _____ By _____

Filed at _____ Date _____