


Index No. C 11

CASS COUNTY LAND CORNER RECORD

T. 142 R. 20 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
C 114 Corner common to sections 4



EXISTING SURVEYS

Original Government Survey

Year surveyed 1928  
Original monument 1X36" I.P.W / BRASS  
CAP

C 114  
54  
1928

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Bearing Trees

Species MAPLE MAPLE \_\_\_\_\_  
Diameter 6" 7" \_\_\_\_\_  
Bearing S10-45E N33W \_\_\_\_\_  
Distance 21KS 51KS \_\_\_\_\_

Original Bearing Trees Found

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration

Year of search \_\_\_\_\_ By \_\_\_\_\_

Bearing Trees, Reference Objects

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Bearing Trees, Reference Objects

\_\_\_\_\_

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_

Remonumentation certificate prepared \_\_\_\_\_ By \_\_\_\_\_

Filed at \_\_\_\_\_ Date \_\_\_\_\_