


Index No. 0-14

CASS COUNTY LAND CORNER RECORD

T. 142 R. 30 M. 5th Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
NW 1/4 Corner common to sections 22



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1918  
Original monument 1" x 3/16" I.P. w/ Br. Cap

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Species	Bearing	Trees
<u>Bass</u>	<u>Oak</u>	
Diameter <u>3</u>	<u>10</u>	
Bearing <u>N</u>	<u>NS 1/2 E</u>	
Distance <u>240 lks</u>	<u>146 lks</u>	

Original Bearing Trees Found

Species	Bearing	Distance
_____	_____	_____
_____	_____	_____
_____	_____	_____
_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1965 By DNR-Engineering  
Location filed Map notes in file  
Monument Found brass cap monument

Evidence of Subsequent Corner Restoration

Year of search 1965 By William Okerman  
found GLO monument in good condition.  
10" OAK NS 1/2 E 96.36' now 13".

Bearing Trees, Reference Objects

Species	Bearing	Distance
_____	_____	_____
_____	_____	_____
_____	_____	_____
_____	_____	_____

Bearing Trees, Reference Objects

<u>Oak</u>	_____	_____
<u>11"</u>	_____	_____
<u>NS 1/2 E</u>	_____	_____
<u>99.20'</u>	_____	_____

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
CERTIFICATE - BILL OKERMAN - 1965

Re-monumentation certificate prepared \_\_\_\_\_

By \_\_\_\_\_

Filed at \_\_\_\_\_

Date \_\_\_\_\_