

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER


W 1/4 Corner of Section 12, Township 143, Range 30, 5 P.M.

STATE OF MINNESOTA, County of CASS

At the corner location shown on the sketch:

- On 8-8-83 found a 1" IRON PIPE MONUMENT WITH BRASS CAP BROKEN IN HALF
DATE
- left monument as found, lowered monument, removed monument (explain)
- On 8-10-83 placed a 3/4" x 5' ALUMINUM PIPE WITH A 3" ALUMINUM CAP IN PLACE
DATE
OF BROKEN MONUMENT IN PLACE

SKETCH OF REFERENCE TIES



Statement of evidence relative to this corner location is on back of page.

I hereby certify that this document and the data contained herein was prepared by me or under my direct supervision.

Walter E. Lewis 8-16-83
SIGNATURE DATE

Registration No. 11395

Land Surveyor, Professional Engineer

County Surveyor, County Engineer

279160
OFFICE OF THE REGISTER OF DEEDS
County of Cass

I hereby certify that this document was filed in the Reg. of Deeds office at 9:40 A.M. on the 3 day of Dec. A.D., 19 84

Register of Deeds Claudine Kayler
By MS, Deputy

DOCUMENT NO. 279160

Statement of Evidence:

IN 1924, EARL HARRINGTON, A U.S. CADASTRAL ENGINEER, FOUND NO EVIDENCE OF THE ORIGINAL $\frac{1}{4}$ SECTION CORNER BETWEEN SECTIONS 11 AND 12. AT THIS POINT HE SET A 1" x 36" IRON PIPE WITH BRASS CAP. AS THIS POINT IS AN OPEN BOG WITH NO TREES CLOSEBY HE SET AN OAK POST NORTH, AND ALONG SIDE OF THE MONUMENT.

ON 8-8-83, WALTER E. CURO AND KEN METCALF, AND GREG CURO, FOUND THE 1" IRON PIPE WITH BRASS CAP BROKEN IN HALF WITH THE ROTTED OAK POST ON THE NORTH SIDE OF IT.

ON 8-10-83, WE SET A $\frac{3}{4}$ " x 5" ALUMINUM PIPE WITH A 3" ALUMINUM CAP, WITH A MAGNETIC INSERT IN ITS PLACE, WITH THE OLD MONUMENT BESIDE IT. THERE ARE NO TREES WITHIN 500 ' SO WE SET 3" x 8' STEEL POST SOUTH AND EAST.