

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER


Northeast Corner of Section 13, Township 141 N, Range 27 W, 5th P.M.

STATE OF MINNESOTA, County of CASS

At the corner location shown on the sketch:

- On 7/8/87 found a 6" diameter concrete post with brass cap, 4" under
DATE
water in grass marsh
 - left monument as found, lowered monument, removed monument (explain)
- On 12/22/87 ~~XXXXXX~~ raised monument-now 1' above water surface
DATE

SKETCH OF REFERENCE TIES



Statement of evidence relative to this corner location is on back of page. 309677

I hereby certify that this document and the data contained herein was prepared by me or under my direct supervision.

Walter C. Cass 1-3-89
SIGNATURE DATE

Registration No. 11395

Land Surveyor, Professional Engineer
 County Surveyor, County Engineer

OFFICE OF THE COUNTY RECORDER
 County of Pear

I hereby certify that this document was filed in the Co. Recorders office at 2:10 P. M. on the 3 day of January A.D., 19 89

County Recorder Clarence Keyler
 By ms, Deputy
 DOCUMENT NO. 309677

Statement of Evidence: Northeast Corner Section 13, T.141 N., R.27 W., 5th P.M.

- 1871 US General Land Office survey set a wood post for this corner and marked the following bearing trees: 16" Elm S 5 W 28 lks., 14" Birch N 70 E 51 lks., 8" Fir N 18 W 32 lks.
- 1936 CCC notes by H Adams show that he found a wood post in poor condition 26" high. Notes also mention 18" Basswood S 51 W 66' with FSLP. Corner in small pothole at end of road.
- 1967 US Forest Service personnel found a burned off scribed post at ground level with 1" I.P. alongside. Also found scribed 20" Basswood S 51 E 66.0'
- 1968 William Okerman filed Affidavit as to Location of Government Corner. He notes evidence found in 1967 and set a 6" diameter x 5' long concrete cylinder with 3" brass tablet. The following bearings were marked: 10" W.Oak S 44 E 91.9' scribed S18 BT, 7" W.Oak S 24 W 72.45' scribed S14 BT, 9" W.Oak N 45 E 92.3' scribed S7 BT, 4" W.Oak N16W 47.3' scribed X BT.
- 1987 On July 8, Curt Krause, US Forest Service Technician and Terry Freeman, Cass County Technician, found the 6" concrete monument 4" under water in grass marsh. Placed 2-6' Steel sign posts and 2-8' Steel sign posts alongside monument to stabilize. 18" Basswood SE is a tipout, Oak SE is now 13", Oak NE is now 10" lightning struck, Oak NW is 4" Oak stub-cut off 8' high, Oak SW is windfall cut off by beaver. 1968 Oaks NE & SE are only good ties available, as whole area is cut over. Placed 8' Steel sign posts (doubled) NE, SE, SW & NW with 6.5' out of marsh. 8' fiberglass sign posts due North & South 4' On Dec. 22, Krause & Freeman raised monument and placed wood post underneath, monument now up 1' out of marsh.