

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER

Standard

South Quarter _____ Corner of Section 34, Township 141 N, Range 30 W, 5th P.M.

STATE OF MINNESOTA, County of Cass

At the corner location shown on the sketch:



Latitude: 46° 58' 48.443"
 Longitude: 94° 27' 35.495"

- On _____ found a _____
DATE
- left monument as found, lowered monument, removed monument (explain)
- On 3/7/89 placed a 2" by 48" iron pipe with brass cap, plastic
DATE
base and magnet.

Magnetic Decl: 5° East
 Not to Scale

SKETCH OF REFERENCE TIES

All distances are horizontal to nail in side of tree.



Monument is located in hardwoods in Northerly ditch of old East-West roadbed.

8' steel sign post East 5.0'
 8' steel sign post West 5.0'

Monument Stamped
 R30W
 SC
 $\frac{1}{4}$ S34 T141N
 1989 T140N
 RLS 17008

All trees are painted with red enamel and marked with a 54-3 (bearing tree) tag.

Statement of evidence relative to this corner location is on back of page.

311858

I hereby certify that this survey, plan or report was prepared by me or under my direct supervision and that I am a duly Registered Land Surveyor under the laws of the State of Minnesota.

David S. Landecker
 David S. Landecker

Date 4-28-89 Registration No. 17008

OFFICE OF THE COUNTY RECORDER

County of Cass

I hereby certify that this document was filed in the Co. Recorders office at 4:06 P. .M. on the 3 day of May A.D., 1989

County Recorder Clondine Kayler

By M.S., Deputy

DOCUMENT NO. 311858

Statement of Evidence:

Standard South Quarter Corner Section 34,
Township 141 North, Range 30 West, Cass County,
Minnesota

Z-15 141-30
Bk.9 Pg.6

1863 Johnson and Thornton, U.S. Deputy Surveyors, originally established this corner position while running the 10th Standard Parallel. The notes indicate a wood post was set to mark the corner position and the following witnesses: a 24 inch White Pine North 37 degrees West a distance of 62 links; and a 12 inch White Birch North 47 degrees East a distance of 86 links.

1938 Civilian Conservation Corps notes show distances along the South line of Sections 33 and 34.

1964 U.S. Forest Service records show the following: technician Ekstrom searched for corner, but found no evidence.

1986 U.S. Forest Service crews set an aerial target in the vicinity of this corner for the search and establishment of the true corner position. The target having coordinate values through the use of GPS on the Chippewa South Boundary Project Cadastral Survey U.S. Project Number 53-6392-8-219. This target allowed for the search and location of this corner.

1988 on August 29 a Landecker-Stevenson & Associates crew searched for the corner. The following information was found and noted: no evidence of iron pipe, post, or bearing trees.

1989 on March 7 a Landecker-Stevenson & Associates crew set a 2 inch by 48 inch iron pipe with brass cap, plastic base and magnet at the lost single proportionate position along the arc of the 10th Standard Parallel between the Southeast and Southwest corners of said Section 34. New bearing trees were marked as shown and steel sign posts are in place as noted on front of this certificate.