

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER

East Quarter Corner of Section 10, Township 141, Range 28, 5th P.M.


STATE OF MINNESOTA, County of Cass

At the corner location shown on the sketch:

- On _____ found a _____
DATE
- left monument as found, lowered monument, removed monument (explain)
- On 10/17/91 placed a 2 inch by 24 inch iron pipe with brass cap
DATE and plastic base with magnet down 10 inches

Magnetic Decl: 5° East SKETCH OF REFERENCE TIES
Not to Scale

All distances are horizontal to nail in side of tree



Monument Stamped
T141N R28W
S 10 $\frac{1}{2}$ S 11
1991
RLS 17008

Monument is located in easterly ditch bottom 25'± easterly of centerline of County Road #126 with field to east
8' steel sign post East 12.15'

All bearing trees are scribed, painted with red enamel and marked with a 54-3 (bearing tree) tag.

Statement of evidence relative to this corner location is on back of page. 334679

I hereby certify that this document and the data contained herein was prepared by me or under my direct supervision.

[Signature] 2/10/92
SIGNATURE DATE

Registration No. 17008

- Land Surveyor, Professional Engineer
- County Surveyor, County Engineer

OFFICE OF THE REGISTER OF DEEDS

County of Cass

I hereby certify that this document was filed in the Reg. of Deeds office at 3:25 P.M. on the 13 day of February A.D., 1992

Register of Deeds [Signature]
By [Signature], Deputy

DOCUMENT NO. 334679

East Quarter corner, Section 10, Township 141
North, Range 28 West, Cass County, Minnesota

G - 17

1874 P.H. Conger, U.S. Deputy Surveyor, originally established this corner position while subdividing Township 141 North, Range 28 West. The notes indicate a wood post was set to mark the corner position and the following witnesses: an 8 inch Poplar North 4 degrees East a distance of 59 links; and a 9 inch Poplar North 48 degrees West a distance of 43 links.

1917 County Surveyor's Record Book "B", pages 601-603 shows a survey by E.B. Horst. The notes indicate that he set the corner proportionally.

1918 General Land Office survey, filed at the Secretary of State, shows that a 1 inch by 36 inch iron pipe with brass cap was set at the proportional position and the following bearing trees marked: a 6 inch Oak North 62 degrees 45 minutes East a distance of 81 links; and a 6 inch White Oak South 73 and 1/2 degrees West a distance of 120 links.

1971 United States Forest Service records in Book 3, page 48 of Township 141 North, Range 28 West, show that Survey Technician Curt Krause searched for the corner. The notes indicate that he found no evidence of the original monument or bearing trees.

1991 on October 17, a Landecker & Associates of Walker, Inc., survey crew search for evidence of previous surveys. Finding no evidence of the previous surveys, they set a 2 inch by 24 inch iron pipe with brass cap and plastic base with magnet at the proportional position between the Northeast and Southeast corners of Section 10. New bearing trees were marked as shown and a steel sign post set as noted on front of this certificate.