

# CERTIFICATE OF LOCATION OF GOVERNMENT CORNER

Witness to  
#32 Meander Corner of Sections 11/14, Township 141, Range 28, 5th P.M.

STATE OF MINNESOTA, County of Cass

At the corner location shown on the sketch:

On 10/28/91 found a 1918 GLO iron pipe (brass cap sheared off)  
DATE


left monument as found,  lowered monument,  removed monument (explain)

On 10/29/91 placed a 2" x 48" iron pipe with brass cap  
DATE

Magnetic Decl: 5° East  
Not to Scale

### SKETCH OF REFERENCE TIES

All distances are horizontal to nail in side of tree



Monument Stamped  
T141N R28W  
←94.11  
WCMC  $\frac{S, 11}{S, 14}$   
1991  
RLS 17008

Monument is located  
84'± easterly of water's  
edge on small ridge

- 8' Steel sign post S 45 E 4.0'
- 8' Steel sign post S 45 W 4.0'
- 8' Steel sign post Easterly 4.0'

All bearing trees are painted with red enamel and marked with a 54-3 (bearing tree) tag.

Statement of evidence relative to this corner location is on back of page. 334683

I hereby certify that this document and the data contained herein was prepared by me or under my direct supervision.

David A. Lindholm 2/10/92  
SIGNATURE DATE

Registration No. 17008

- Land Surveyor,  Professional Engineer
- County Surveyor,  County Engineer

### OFFICE OF THE REGISTER OF DEEDS

County of Cass

I hereby certify that this document was filed in the Reg. of Deeds office at 3:45 P. M. on the 13 day of January A.D., 1992

Register of Deeds Clairline Kaylor

By m, Deputy

DOCUMENT NO. 334683

Witness corner to Meander corner #32, Sections 11 and 14, Township 141 North, Range 28 West, Cass County, Minnesota

J 20-21

1874 P.H. Conger, U.S. Deputy Surveyor, originally established this corner position while subdividing Township 141 North, Range 28 West. The notes indicate a wood post was set to mark the corner position. No bearing trees were marked.

1918 General Land Office survey shows that a 3 foot long iron post 1 inch in diameter with brass cap was set at the shore of the lake at the proportional position. The following bearing trees were marked: a 3 inch Poplar North 60 degrees East a distance of 133 links; and a 4 inch Poplar South 75 and 1/2 degrees East a distance of 498 links.

1972 United States Forest Service records in Book 1, page 33 of Township 141 North, Range 28 West, show the following: James Ekstrom searches from section corner to this corner. Corner falls in lake. No evidence was found of this corner position or its accessories.

1991 on October 28, a Landecker & Associates of Walker, Inc., survey crew find 1 inch General Land Office iron pipe with cap sheared off leaning in water 10 feet westerly of waters edge. The found iron fits the computed location for the corner and is accepted as the 1918 General Land Office corner. On October 29, a Landecker crew set a 2 inch by 48 inch iron pipe with brass cap up 10 inches for Witness corner to the 1918 General Land Office position for the Meander corner now in the lake. Bearing trees were marked as shown and steel sign posts set as noted on front of this certificate.