

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER


North Quarter _____ Corner of Section 29, Township 141, Range 31, 5th P.M.
 STATE OF MINNESOTA, County of Cass

At the corner location shown on the sketch:

- On _____ found a _____
DATE
- left monument as found, lowered monument, removed monument (explain)
- On 11/16/92 placed a 2 inch by 48 inch iron monument with brass
DATE
cap up 14 inches.

Magnetic Decl: 5° East SKETCH OF REFERENCE TIES
 Not to Scale

All distances are horizontal to nail in side of tree



Monument is located 450'± southeasterly of Forest Service Road #2804A. 8' steel sign post North 2.85'

Monument Stamped:
 T141N R31W
 $\frac{1}{4}$ S20
 S29
 1992
 RLS 21367

All bearing trees are scribed, painted with red enamel and marked with a 54-3 (bearing tree) tag.

Statement of evidence relative to this corner location is on back of page. 343560

I hereby certify that this survey, plan or report was prepared by me or under my direct supervision and that I am a duly Registered Land Surveyor under the laws of the State of Minnesota.

Terry L. Freeman
 Terry L. Freeman
 Date 12/8/92 Registration No. 21367

OFFICE OF THE COUNTY RECORDER
 County of Cass

I hereby certify that this document was filed in the Co. Recorders office at 3:25 P.M. on the 8 day of December A.D., 1992
 County Recorder Chardine Keyler
 By MJ, Deputy
 DOCUMENT NO. 343560

Statement of Evidence:

North Quarter corner, Section 29, Township 141
North, Range 31 West, Cass County, Minnesota

R-7

1873 P.H. Conger, U.S. Deputy Surveyor, originally established this corner position while subdividing Township 141 North, Range 31 West. The notes indicate that he set a wood post and marked the following bearing trees: an 8 inch Jack Pine North 20 degrees West a distance of 84 links (55.44 feet); and an 8 inch Jack Pine South 60 degrees East a distance of 90 links (59.40 feet).

1961 United States Forest Service notes for Township 141 North, Range 31 West, in Book 2, page 15, show search by R.H. McDonald. The notes indicate that he did not find any evidence of the original corner.

1973 United States Forest Service notes on corner card indicate that on September 14, United States Forest Service employee, Curt Krause, searched for corner, but found nothing.

1975 on April 29, R.F. Schneider, Licensed Land Surveyor Number 5740, search for corner and found nothing. His notes in Book 37, page 64, indicate that he set a spike at the single proportion position and marked the following bearing trees: a 10 inch White Oak South 80 degrees West a distance of 39.52 feet and an 8 inch White Oak North 12 degrees East a distance of 39.26 feet.

1977 on March 21, United States Forest Service notes on corner card indicate that a United States Forest Service technician found the 1975 spike and ties.

Notes for Township 141 North, Range 31 West, Book 2, page 15, indicate that United States Forest Service employee, Curt Krause, set a 2 inch by 60 inch iron pipe with brass cap in place of the 1975 spike and marked the following bearing trees: a 9 inch White Oak North 56 degrees East a distance of 13.09 feet; a 9 inch White Oak South 39 degrees West a distance of 52.50 feet; a 12 inch Red Oak North 78 degrees West a distance of 37.70 feet; and a 10 inch Red Oak South 4 degrees West a distance of 22.12 feet.

R.F. Schneider, Licensed Land Surveyor Number 5740, filed a corner certificate with the 1977 United States Forest Service information.

1992 on October 9, a Landecker & Associates of Walker, Inc., survey crew found the United States Forest Service monument and 1977 ties.

1992 on November 16, a Landecker & Associates of Walker, Inc., survey crew set a 2 inch by 48 inch iron monument with brass cap up 14 inches at the lost, single proportion position between the Northwest and Northeast corners of Section 29 (see note below).

New bearing trees were marked as shown and a steel sign post set as noted on front of this certificate.

Note: This corner position is different than that established by R.F. Schneider in 1975 and monumented in 1977 by the United States Forest Service due to the recovery of the obliterated position of the true original corner at the Northwest corner of Section 21 from which the Southwest corner of Section 21 was then established by double proportion methods. The 1975 survey used a different double proportion position.