

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER

East Quarter _____ Corner of Section 27, Township 141, Range 27, 5th P.M.

STATE OF MINNESOTA, County of Cass

At the corner location shown on the sketch:

On 12/10/93 found a 2 inch iron pipe with brass cap
DATE


left monument as found, lowered monument, removed monument (explain)

On _____ placed a _____
DATE

Magnetic Decl: 5° East
Not to Scale

SKETCH OF REFERENCE TIES

All distances are horizontal to nail in side of tree



Monument is located 55'± N 45 degrees E of the centerline of Forest Service Road Number 2566. Monument is up 18 inches.
 4 inch by 4 inch Cedar post West 6.7'.
 8 foot steel sign post South 3.7' with old 2" pipe alongside
 8" White Oak S 42 W 10.00' (1968 USFS BT)

MONUMENT STAMPED:
 T141N R27W
 S27 S26
 1968
 RLS No. 6807

All bearing trees are scribed, painted with red enamel and marked with a 54-3 (bearing tree) tag.

Statement of evidence relative to this corner location is on back of page.

357311

I hereby certify that this survey, plan or report was prepared by me or under my direct supervision and that I am a duly Registered Land Surveyor under the laws of the State of Minnesota.

Terry L. Freeman
 Terry L. Freeman
 Date 5/4/94 Registration No. 21367

OFFICE OF THE COUNTY RECORDER
 County of CASS

I hereby certify that this document was filed in the Co. Recorders office at 10:10 A. M. on the 4th day of MAY A.D., 19 94

County Recorder Claudia Kayler
 By N.O. ROEHL M, Deputy
 DOCUMENT NO. 357311

Statement of Evidence:

East Quarter corner, Section 27, Township 141 North,
Range 27 West, Cass County, Minnesota

T-17

1874 P.H. Conger, U.S. Deputy Surveyor, originally established this corner position while subdividing Township 141 North, Range 27 West. The notes indicate that he set a wood post and marked the following bearing tree: a 9 inch White Birch North 20 degrees East a distance of 20 links (13.20 feet).

1920 Cass County Surveyor's Office Record Book "C", Page 379, shows a survey by Lincoln Mackey. The notes indicate that he set a 2 inch by 48 inch iron monument proportionally and marked the following bearing trees: an 8 inch White Oak South 35 and 1/4 degrees West a distance of 36.4 feet; and a 6 inch White Ash South 45 degrees East a distance of 26.3 feet.

1940 Civilian Conservation Corps notes on Form 874 on file in United States Forest Service office in Cass Lake, Minnesota, shows a survey by R.T. DeFant. The notes indicate that he found a pipe up 20 inches in good condition. He placed a Forest Service Location Poster on a 10 inch Elm North 36 degrees East a distance of .13 chains (8.6 feet).

1968 United States Forest Service notes for Township 141 North, Range 27 West, in Book 2, Page 38, show that United States Forest Service Technicians found a 2 inch by 48 inch iron monument and the following bearing trees: an 8 inch White Oak South 35 and 1/4 degrees West a distance of 36.4 feet, now 12 inches; a 6 inch White Ash South 45 degrees East a distance of 26.3 feet, now a stump hole. The notes state that they set a pipe with a 3 inch stamped brass tablet and marked the following new bearing trees: a 6 inch White Oak South 42 degrees West a distance of 10.0 feet; a 14 inch White Oak North 54 degrees East a distance of 76.15 feet; and a 14 inch White Oak North 20 degrees West a distance of 51.25 feet. They also set a 4 inch by 4 inch by 72 inch "red top" Cedar post West a distance of 6.7 feet.

1971 William Okerman, Registered Land Surveyor Number 6807, and United States Forest Service Surveyor, filed an "Affidavit As To Location Of Government Corner" showing the 1968 United States Forest Service information.

1977 Okerman Surveying, while working in Section 26, locate and use monument as established in 1920 for corner.

1977 United States Forest Service notes on file in office in Cass Lake, Minnesota, for Township 141 North, Range 27 West, in Book 2, Page 38, show that United States Forest Service Technicians found the 1968 monument, bearing trees and sign post standing in good condition.

1993 on December 11, a Landecker & Associates, Inc. survey crew found a 2 inch iron pipe with brass cap up 18 inches and the 1968 bearing trees in good condition. They set a new steel sign post as noted on front of this certificate.

Landecker & Associates, Inc. accepts this monument as a perpetuation of the corner set at the lost, single proportion position in 1920.