

# CERTIFICATE OF LOCATION OF GOVERNMENT CORNER

East Quarter corner of Section 01, Township 143 N., Range 30 W., 5th P.M.  
 State of Minnesota, County of Cass

At the corner location shown on the sketch:


On 06-16-2011 found a 1" iron pipe with a 2.5" diameter cap,  
 6" above the surface grade.

left monument as found     lowered monument     removed monument (explain)

On \_\_\_\_\_ placed \_\_\_\_\_




## SKETCH OF REFERENCE TIES (NOT TO SCALE)



NOTE: All bearings are true.

Statement of evidence relative to this corner location is on the back of this page.

I hereby certify that this survey, plan, or report was prepared by me or under my direct supervision and that I am a duly Licensed land Surveyor under the laws of the State of Minnesota. I further certify that this United States public land survey monument record is correct and complete to the best of my knowledge and belief.

  
 Terry L. Freeman, Land Surveyor

Date 12/9/11 MN License No. 21367

**A000578299**  
**OFFICE OF COUNTY RECORDER**  
**CASS COUNTY MINNESOTA**  
**CERTIFIED, FILED, AND/OR**  
**RECORDED ON**  
**03/01/2012 2:29:35 PM**  
**AS DOC #: A000578299**  
**PAGES: 2 REC FEES: 0.00**  
**KATHRYN M. NORBY**  
**COUNTY RECORDER**

Index No. C.0 - 25.0

**STATEMENT ON EVIDENCE**

**East Quarter Corner of Section 1, Township 143 North, Range 30 West of the 5th Principal Meridian.**

In 1873, P.H. Conger, U.S. Deputy Surveyor, set a wood post in place to mark the location of this corner and established bearing trees as follows: a 5" Tamarack, N80°E 10 links; and an 8" Tamarack, S8°W 9 links.

1900, U.S. Army Corp of Engineers map for the Leech Lake Reservoir shows corner found by surveyor Horace Dunaway. Copy of map on file in the Cass County Survey Department.

In 1924, Earl G. Harrington, U.S. Cadastral Engineer, found a wood stake and both original BT's. He set a 1x36" iron pipe with a brass cap and established two new bearing trees as follows: a 7" Spruce, N13°30'W 38links; and a 5" Spruce, S29°E 35 links. Information on file in the Cass County Surveyors office.

In 1993, Curt Kruse, U.S.F.S. personnel, found GLO monument tipped. He stood it upright which checks with the well rotted remains of both original BT's and stump of northwest GLO BT and windfall of southeast GLO BT. He marked new ties: a 7" Black Spruce, N6°W 27.02 feet; a 5" Cedar, N45°E 13.75 feet; a 6" Cedar, S23°W 8.12 feet; and steel sign posts North 2.65 feet and East 3.25 feet. Information on file in the U.S.F.S. Cass Lake office T143N R30W Book 1, Page 42.

In 1999, Certificate of Survey by Terry Freeman, RLS 21367 shows corner found.

On June 16, 2011, a Northern Engineering & Consulting survey crew found a 1" iron pipe with a 2-1/2" diameter cap, 6" above the surface grade. Five existing ties were found as shown on the front page of this certificate. Brass Cap monument accepted as a perpetuation of the original corner.

**Minnesota State Plane (Central Zone)**

Northing 1141313.008  
Easting 2586443.067

**County Coordinates (Cass County North)**

Northing 255555.241  
Easting 453493.3