

# CERTIFICATE OF LOCATION OF GOVERNMENT CORNER

NE Corner of Section 33, Township 138N, Range 31W, 5th p.m., State of Minnesota, County of Cass


At the corner location shown on the sketch:

On 11/06/2012 found a 1 1/8" DIA. IRON PIPE  
Date

left monument as found      lowered monument      removed monument (explain)

On \_\_\_\_\_ placed a \_\_\_\_\_  
Date

### SKETCH OF REFERENCE TIES




Tie Distances are measured to the spikes.

Cass County Coordinate System (South Zone)  
N= 310032.7396 E= 466905.4790

○ Set Re-Rod with RLS cap No. 17774

● Found Pipe



NOT TO SCALE

Statement of evidence relative to this corner location is on back of page.

I hereby certify that this document and the data contained herein was prepared by me or under my direct supervision.

*Marvin R. Kohout* 12 Aug 2014  
Marvin R. Kohout Date

License No. 17774

Land surveyor

OFFICE OF COUNTY RECORDER



A000604902

OFFICE OF THE COUNTY RECORDER  
CASS COUNTY, MINNESOTA  
CERTIFIED, FILED, AND/OR  
RECORDED ON

8/20/2014 11:22:47 AM

AS DOC #: A000604902

PAGES: 2

REC FEES: 0.00

KATHRYN M. NORBY  
CASS COUNTY RECORDER

BY SR \_\_\_\_\_ Dep

Page 1 of 2 A000604902



INDEX NO. V.0 - 13.0

STATEMENT OF EVIDENCE

**NORTHEAST CORNER SECTION 33, TOWNSHIP 138N, RANGE 31W, 5<sup>TH</sup> P.M.**

NOV. T.B. WALKER, GENERAL LAND OFFICE (GLO) DEPUTY SURVEYOR SET A POST  
 1870 FOR THE ORIGINAL CORNER AND MARKED B.T.'S. REFERENCES ARE:

8" CEDAR	8" CEDAR	6" CEDAR	10" CEDAR
N 60 E	S 51 E	S 41 W	N 74 W
10 LKS	11 LKS	8 LKS	12 LKS

OCT. J.A. JOHNSTON, CASS COUNTY, STATES, AT 5280 FEET WE SEARCH FOR CORNER  
 1915 27-28-33-34, AND, PLACE HUB AT 5308.55 FEET AND OFFSET HUB 5.075 FEET WEST  
 ON TRUE N-S LINE AS TEMPORARY COR. SURVEY RECORD NO. 365, BOOK "B" PAGE  
 587, CURO BOOK 89, PG 37-39

NOV. E.B. HORST, LS NO. 376, DEPUTY COUNTY SURVEYOR STATES, AT COR. TO  
 1916 SECS. 27-28-33-34 SET I. M. SURVEY RECORD NO. 350, BOOK "B" PAGE 537

OCT. E.B. HORST, LS NO. 376, DEPUTY COUNTY SURVEYOR STATES, WHEN I WAS IN THE  
 1917 VICINITY OF THE CORNER TO SECTIONS 27-28-33-34 I LOOKED FOR THE BEARING  
 TREES TO THIS CORNER WHICH J.A. JOHNSTON WAS UNABLE TO FIND THE TIMBER  
 BEING DOWN FLAT. I MAKE A THURO SEARCH AND FIND THE 8" CEDAR N60E 10  
 BLOWN DOWN AND COVERED WITH MOSS, VERY ROTTED BUT STILL BEARING  
 THE B.T. ON THE STUMP I ALSO FIND 10" CEDAR N74W 12 WHICH WAS LAYING  
 FACE DOWN AND NEARLY COVERED BY VEGETATION, CUT THIS TREE OFF ABOUT  
 8' ABOVE THE STUMP TO DRIVE THIS CORRECTION HUB, THE OTHER TREES ARE  
 ENTIRELY ROTTED AWAY. FROM THE ABOVE TREES I CHECK THE IRON MON. SET  
 BY E.B. HORST & KINNEY AND FIND THE IRON MONUMENT TO BE 1.7' NORTH AND  
 0.3' EAST OF THE TRUE SECTION CORNER. CURO BOOK 53 PAGE 68

AUG. B. HIPPEN, CCSO TECHNICIAN, RECORDS OF THE CCSO, SET A 1 1/8" OUTSIDE  
 2005 DIAMETER IRON PIPE, DOWN 0.3', 2' +/- WEST OF CENTERLINE OF 60<sup>TH</sup> AVE. AT THE  
 HORST POSITION PROPORTIONALLY BETWEEN THE RECOVERED NORTHEAST  
 CORNER OF SECTION 28 AND THE RECOVERED SOUTHEAST CORNER SECTION  
 SECTION 33. REFERENCES ARE:

8" ASH	10" ASH	8" ASH	16" ASH
N 47 E	S 55 E	S 77 W	N 67 W
65.11	47.62	52.45	45.62

2012 MARVIN KOHOUT, LS NO. 17774, AND DOUG STILLE, TECHNICIAN, OF KOHOUT  
 LAND SURVEYING, FOUND THE PIPE SET BY HIPPEN AND ACCEPTS IT AS MARKING  
 THE LOCATION OF THE NE CORNER OF SECTION 33. THE 2005 TIES ARE GOOD.