

Page 1 of 2 A000651788



A000651788

OFFICE OF THE COUNTY RECORDER  
CASS COUNTY, MINNESOTA  
CERTIFIED, FILED, AND/OR  
RECORDED ON

7/25/2019 12:40:31 PM

AS DOC #: A000651788

PAGES: 2

REC FEES: 0.00

KATHRYN M. NORBY  
CASS COUNTY RECORDER

BY SF \_\_\_\_\_ Dep TX#: 155173

Twp 144 Rge 25 Index No. V.0-07.0

### CERTIFICATE OF LOCATION OF GOVERNMENT CORNER

North Quarter corner of Section 32, Township 144 N., Range 25 W., 5th P.M.  
State of Minnesota, County of Cass


At the corner location shown on the sketch:

On 18 July 2019 found a 1.5 inch magnetic concrete nail, set from witnesses in  
2011, 0.5 foot south of the centerline of CSAH #3.

left monument as found     lowered monument     removed monument (explain)

On \_\_\_\_\_ placed \_\_\_\_\_

#### SKETCH OF REFERENCE TIES NOT TO SCALE



Statement of evidence relative to this corner location is on the back of this page.

I hereby certify that this survey, plan or report was prepared by me or under my direct supervision and that I am a duly Licensed Land Surveyor under the laws of the State of Minnesota.

Terry L. Freeman, Cass County Surveyor  
Date 7/24/19 MN License No. 21367

Statement of Evidence

North Quarter corner of Section 32, Township 144 North, Range 25 West, 5th Principal Meridian.

1983 Cass County Highway Department(CCHD), S.P. 11-603-07, on file in the CCHD, plan indicates subject corner assumed at Station 258+49.8.

May 1985 J. Parker, LS 9235, under contract with the United States Forest Service (USFS), set a 5/8 inch diameter by 36 inch aluminum rod with a stamped 3 inch aluminum cap in the lost position, 0.3 foot below the road surface, on centerline of CSAH #3. He recorded a Certificate of Location of Government Corner in the Cass County Recorders Office(CCRO) on May 15, 1985 as Document Number 281973. The document indicates the corner was witnessed as follows:

12" N. Pine N 21° E 71.20 feet 8" Maple S 45° E 93.80 feet

July 2011 B. Hippen, technician, records of the Cass County Highway Department, Survey Office(CCHD/SO), prior to reconstruction of CSAH #3, set concrete nail from recovered witnesses, on centerline of CSAH #3, 3 feet, more or less, west of a fence to the south and added witness as follows:

12" Spruce N 18° W 95.14 feet Steel Sign Post S 3° W 62.3 feet

Aug. 2011 B. Hippen, technician, records of the CCHD/SO, set a magnetic concrete nail from witnesses 0.5 foot south of the new centerline of CSAH #3.

July 2019 B. Hippen, technician, records of the CCHD/SO, found a magnetic concrete nail 0.5 foot south of the centerline of CSAH #3 and the following witnesses;

12" N. Pine(1985) N 21° E 71.20 feet 8" Maple(1985) S 45° E 93.80 feet  
Steel Sign Post(2011) S 3° W 62.3 feet 10" Maple N 40° W 94.88 feet

The recovered and established witnesses for this corner position are shown on the face of this document.

Analysis of the recovered record data, field evidence and survey measurements, indicates that the position recovered in 2011 by the CCHD/SO, is the accepted location of this corner.

County Coordinates (Cass County North)

Northing 263572.30

Easting 586005.29