



A000652198

OFFICE OF THE COUNTY RECORDER
CASS COUNTY, MINNESOTA
CERTIFIED, FILED, AND/OR
RECORDED ON

8/8/2019 11:09:08 AM

AS DOC #: A000652198

PAGES: 2

REC FEES: 0.00

KATHRYN M. NORBY
CASS COUNTY RECORDER

BY KF Dep TX#: 155513

Page 1 of 2 A000652198

Twp 143 Rge 27 Index No. V.0-23.0


CERTIFICATE OF LOCATION OF GOVERNMENT CORNER

North Quarter corner of Section 36, Township 143 N., Range 27 W., 5th P.M.
State of Minnesota, County of Cass

At the corner location shown on the sketch:

On 16 May 2001 found a 2.5 inch ODIP with brass cap, down 0.1 foot,
1' ± South of the centerline of CSAH #4.

left monument as found lowered monument removed monument (explain)
On 8 Nov 2006 placed a 2.5 inch ODIP with brass cap, down 0.05 foot,
On the new centerline of CSAH #4.



NOTE:
All bearings are true

Statement of evidence relative to this corner location is on the back of this page.

I hereby certify that this survey, plan or report was prepared by me or under my direct supervision and that I am a duly Licensed Land Surveyor under the laws of the State of Minnesota.

Terry L. Freeman, Cass County Surveyor
Date 8/7/19 MN License No. 21367

Statement of Evidence**North Quarter corner of Section 36, Township 143 North, Range 27 West, 5th Principal Meridian.**

- July 1999 L. Leuelling, LS 16089, filed a Certificate of Location of Government Corner in the Cass County Recorders Office as Document Number 414548.
- Sept. 2000 Cass County Highway Department personnel during road construction found the Southeast trees are stubs so the following witnesses are added:
P. Pole S 66° E 99.70 feet 8" Aspen S 02° E 74.81 feet
- May 2001 B. Hippen and E. Shelly, technicians, records of the Cass County Highway Department, Surveyor's Office (CCHD/SO), removed the galvanized steel pipe with brass capped prior to road construction.
- Nov. 2006 B. Hippen, technician, records of the CCHD/SO, reset the galvanized steel pipe with brass capped after completion of road construction from existing witness trees.
- July 2019 B. Hippen, technician, records of the CCHD/SO, found the United States Department of Agriculture, Forest Service(USFS) brass capped monument and the 1999 and 2000 witnesses in good condition.

The monument, together with the recovered and established references for the position are shown on the face of this document.

Analysis of the recovered record data, field evidence and survey measurements, indicates that the monument reset by CCHD/SO in 2006 is the accepted location of this corner.

County Coordinates (Cass County North)**Northing 232753.62****Easting 543972.87**