

Page 1 of 2  
A000674065



A000674065

OFFICE OF THE COUNTY RECORDER  
 CASS COUNTY, MINNESOTA  
 CERTIFIED, FILED, AND/OR  
 RECORDED ON  
 6/30/2021 10:05:37 AM  
 AS DOC #: A000674065  
 PAGES: 2  
 REC FEES: 0.00  
 KATHRYN M. NORBY  
 CASS COUNTY RECORDER  
 BY NG Dep TX#: 173051


Index No. L-5

**CERTIFICATE OF LOCATION OF GOVERNMENT CORNER**

INDEX NO. L-5, East Quarter CORNER OF SECTION 18, TOWNSHIP 143, RANGE 27,  
 STATE OF MINNESOTA, COUNTY OF CASS.

AT THE CORNER LOCATION SHOWN ON THE SKETCH:

- ON 05-04-2021 FOUND A(N) Nothing
- LEFT MONUMENT AS FOUND,  LOWERED MONUMENT,  REMOVED MONUMENT (EXPLAIN)
- ON 05-04-2021 PLACED A(N) 1/2"x60" Iron pipe with plastic cap stamped "KRAMER 23668", up 1.0'.



I hereby certify that this survey, plan, or report was prepared by me or under my direct supervision, and that I am a duly Licensed Land Surveyor under the laws of the State of Minnesota. I further certify that this certificate of location of government corner is correct and complete to the best of my knowledge and belief.

Signature: James Kramer

Date: 6-04-2021

Reg. No. 23668

NAD 1983/1996 CASS COUNTY COORDINATES  
 N= 245966.575 E= 519946.810

Coordinates derived by RTK GPS (survey grade)

SKETCH OF REFERENCE TIES  
 (not to scale - bearings are magnetic)  
 Ties are measured to center of monument unless otherwise noted

UNITS =  Metric  English

**KLD**  
 1120 Industrial Park Road SW  
 Bremerton, WA 98311  
 206-829-4333  
 KRAMER LEAS DELEO  
 SURVEYING • ENGINEERING • PLANNING  
 BRAINERD ST. CLOUD

STATEMENT OF EVIDENCE RELATIVE TO THIS CORNER LOCATION IS ON THE BACK OF THE PAGE



L.O-5.0

**STATEMENT OF EVIDENCE:**

EAST QUARTER CORNER OF SECTION 18,  
TOWNSHIP 143 NORTH, 27 RANGE WEST, CASS  
COUNTY, MINNESOTA

**1873** The original public land survey was completed and a wood post was set to mark the corner along with the following bearing ties. Information on file in the Mn historical Society, St. Paul MN. Copies on file in the Cass County Highway Department/Surveyors Office (CCHD/SO).

5" Spruce	N77W	8 links (5.28)
5" Spruce	N65E	21 links (13.86)

William Allen  
US Deputy Surveyor

**2021** Crews at Kramer Leas Deleo searched for original corner evidence and bearing ties and found nothing. It was determined the corner location is lost, the corner location was derived by proportional measure between the Northeast and Southeast corners of Section 18. A 1/2" x 60" iron pipe with a plastic cap stamped "KRAMER 23668" to mark the corner. The following bearing ties were set.

6" Tamarack	N46E	10.66
4" Tamarack	S55W	18.58

For additional information contact:  
**Kramer Leas Deleo PC**  
1120 Industrial Park Road Southwest  
Brainerd, MN. 56401  
218-829-5333