


Index No. A 7

CASS COUNTY LAND CORNER RECORD

T. 134 R. 31 M. 5TH Coordinates: X _____ Y _____
N/4 5 Corner common to sections 5 AND 32-135-31



EXISTING SURVEYS

Original Government Survey

Year surveyed 1858

Original monument lost

Species	Bearing	Trees
<u>ASPEN</u>	<u>ASPEN</u>	
Diameter <u>5"</u>	<u>5"</u>	
Bearing <u>N37E</u>	<u>SOUTH</u>	
Distance <u>5 LKS</u>	<u>4 LKS.</u>	

Original Evidence Found

Year of search _____ By _____

Monument found _____

Original Bearing Trees Found

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed _____

Monument _____

Evidence of Subsequent Corner Restoration

Year of search 1993 October By Thomas Thiessen

Placed 1 1/2" iron pipe monument capped RLS 16097.

4-26-94 Cert Filed by Thomas Thiessen, RLS

#16097, Doc. #3570999

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance
<u>White Oak</u>	<u>3"</u>		<u>17.95</u>
<u>Aspen</u>	<u>4"</u>		<u>12.53</u>
<u>White Oak</u>	<u>6"</u>		<u>50.41</u>
<u>White Oak</u>	<u>12"</u>		<u>77.79</u>

Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed _____

Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____ By _____

Filed at _____ Date _____