


Index No. C 9

CASS COUNTY LAND CORNER RECORD

T. 134 R. 32 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
E/45 Corner common to sections 4, 5, 8



EXISTING SURVEYS

Original Government Survey  
 Year surveyed 1870  
 Original monument POST

Original Evidence Found  
 Year of search \_\_\_\_\_ By \_\_\_\_\_  
 Monument found \_\_\_\_\_

Species	Bearing	Trees
<u>BL. PINE</u>	<u>BL. PINE</u>	
Diameter <u>5"</u>	<u>5"</u>	
Bearing <u>S30W</u>	<u>S75E</u>	
Distance <u>216KS</u>	<u>256KS</u>	

Original Bearing Trees Found  
 Species \_\_\_\_\_  
 Diameter \_\_\_\_\_  
 Bearing \_\_\_\_\_  
 Distance \_\_\_\_\_

Subsequent Corner Restoration  
 Year surveyed 12/24/91 By Thomas Thiessen  
 Location filed Cert. Filed Doc. # 343234  
 Monument Set 1/2" iron pipe monument capped  
RLS No. 16097.

Evidence of Subsequent Corner Restoration  
 Year of search \_\_\_\_\_ By \_\_\_\_\_

Species	Bearing	Trees, Reference Objects
<u>Jack Pine</u>	<u>Jack Pine</u>	<u>Jack Pine</u>
Diameter <u>10"</u>	<u>8"</u>	<u>6"</u>
Bearing <u>North</u>	<u>NE</u>	<u>SE</u>
Distance <u>37.07'</u>	<u>18.10'</u>	<u>35.36'</u>

Bearing Trees, Reference Objects  
 \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_

Subsequent Corner Restoration  
 Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
 Location filed \_\_\_\_\_  
 Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found  
 Year of search \_\_\_\_\_ By \_\_\_\_\_  
11-24-92 Cert. Filed by Thomas Thiessen,  
RLS 16097, Doc. # 343234.

Remonumentation certificate prepared \_\_\_\_\_  
 Filed at \_\_\_\_\_

By \_\_\_\_\_  
 Date \_\_\_\_\_