Index No. E11

CASS COUNTY LAND CORNER RECORD

T. 135 R. 30 M. 5TH Coordinates: X _____ Y _____

N1/4 9 Corner common to sections 4, 9



O = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1869

Original monument POST

Original Evidence Found

Year of search _____ By _____

Monument found _____

Bearing Trees

Species	BIRCH	SPRUCE		
Diameter	7"	10"		
Bearing	S80W	NORTH		
Distance	15 LKS.	12 LKS.		

Original Bearing Trees Found

Species				
Diameter				
Bearing				
Distance				

Subsequent Corner Restoration

Year surveyed 6/2002 By CCSO

Location filed _____

Monument Found 7/8" ODIP, RLS 17056, down 0.5', top bent, 9' ± S of ℄ CR #108, 14' ± W of fence North.

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Species	Ash	Ash	W. Oak	fence cor
Diameter	6"	8"	20"	
Bearing	S20°E	S22°W	N26°W	N20°E
Distance	48.71'	53.98'	147.38°	46.40'
	dbl hd nail	dbl hd nail	dbl hd nail	dbl hd nail

Bearing Trees, Reference Objects

Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed _____

Monument _____

March 1923

Twp Road Order shows no survey

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____ By _____

Filed at _____ Date _____