Index No. V 23

# CASS COUNTY LAND CORNER RECORD

T. 135 R. 30 M. 5TH Coordinates: X _____ Y _____

N 1/4 36 Corner common to sections 25, 36




O = Corner

## EXISTING SURVEYS

### Original Government Survey

Year surveyed 1869

Original monument Post

### Original Evidence Found

Year of search _____ By _____

Monument found _____

### Bearing Trees

| | | | | |
|---|---|---|---|---|
| Species | TAM | TAM | | |
| Diameter | 4" | 6" | | |
| Bearing | NRW | S15W | | |
| Distance | 8 LKS. | 12 LKS | | |

### Original Bearing Trees Found

| | | | | |
|---|---|---|---|---|
| Species | | | | |
| Diameter | | | | |
| Bearing | | | | |
| Distance | | | | |

### Subsequent Corner Restoration

Year surveyed 1999 By DNR J. Walker

Location filed State of MN & Cass Co.

Monument No monument set. Land owner would not allow access.

### Evidence of Subsequent Corner Restoration

Year of search 1997 By MNDNR, J. WALKER

SEARCH OF AREA RECOVERED NO EVIDENCE TO DISPUTE A LOST POSITION. OWNER DENIED FURTHER ACCESS. NO MONUMENT WAS SET.

CERT. OF LOCATION, MAY '99, DOC. #412425

### Bearing Trees, Reference Objects

| | | | | |
|---|---|---|---|---|
| Species | | | | |
| Diameter | | | | |
| Bearing | | | | |
| Distance | | | | |

### Bearing Trees, Reference Objects

NO MONUMENT SET

### Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed _____

Monument _____

### Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____ By _____

Filed at _____ Date _____