Index No. V-13, 14

CASS COUNTY LAND CORNER RECORD

T. 136 R. 29 M. 5TH Coordinates: X _____ Y _____

MC #18 Corner common to sections 27 & 34

EAST SIDE MAYO LAKE



O = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed DECEMBER 1870

Original monument POST

Original Evidence Found

Year of search _____ By _____

Monument found _____

Bearing Trees

Species	N. PINE	NO OTHER TREES NEAR	
Diameter	16"		
Bearing	S68E		
Distance	180 lks		

Original Bearing Trees Found

Species			
Diameter			
Bearing			
Distance			

Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed _____

Monument _____

Evidence of Subsequent Corner Restoration

Year of search 6/30/81 By D. LANDECKER

FOUND 2" IRON PIPE WITH STAMPED OBLONG CAP.
TESTIMONY OF CLARENCE HERTIG, LOCAL OWNER,
D. ANDERSON WAS AT COR. IN 1953.
NORTH 15 ± TO EDGE MARSH

Bearing Trees, Reference Objects

Species				
Diameter				
Bearing				
Distance				

Bearing Trees, Reference Objects

BUR OAK	ASH	R. OAK	ASH
18"	18"	12"	16"
EAST	EAST	S40E	S30W
30.10	17.18	52.55	5.23

NSCS UP 3'±, DBL BLAZED

Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed _____

Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____ By _____

Filed at _____ Date _____