


Index No. 211

CASS COUNTY LAND CORNER RECORD

T. 137 R. 30 M. 5TH Coordinates: X _____ Y _____
514 33 Corner common to sections 33



○ = Corner

EXISTING SURVEYS

Original Government Survey
Year surveyed 1858
Original monument Post

Original Evidence Found
Year of search _____ By _____
Monument found _____

Bearing Trees
Species W. Birch DEAD ASPEN
Diameter 6" 6"
Bearing N52°14'E N61°12'W
Distance 170 LKS 26 LKS

Original Bearing Trees Found
Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration
Year surveyed 1977 By R.F. Schneider for
Location filed Co Hwy Dept - Co Rd # 28
Monument Corner position from Road stationing

Evidence of Subsequent Corner Restoration
Year of search 5/01 By CCSO
Found Alon cap monument on E
Co. Rd. #28 and tree line North

Bearing Trees, Reference Objects
Species _____
Diameter _____
Bearing _____
Distance _____

Bearing Trees, Reference Objects
Aspen cmP cmP
9" 30" 30"
N24°E S60°W N54°W
78.41' 86.76' 86.59'

Subsequent Corner Restoration
Year surveyed _____ By _____
Location filed _____
Monument -Corner GPS 9/17/02 CCSO
Alon cap on E #28

Evidence of Subsequent Corner Restoration Found
Year of search _____ By _____

Remonumentation certificate prepared _____ By _____
Filed at _____ Date _____