


Index No. 219

CASS COUNTY LAND CORNER RECORD

T. 137 R. 32 M. 5TH Coordinates: X _____ Y _____
514 35 Corner common to sections 35



EXISTING SURVEYS

Original Government Survey

Year surveyed 1858

Original monument Post

Original Evidence Found

Year of search _____ By _____

Monument found _____

Bearing Trees

Species	<u>BALM GILEAD</u>	<u>BALM GILEAD</u>	_____	_____
Diameter	<u>10"</u>	<u>12"</u>	_____	_____
Bearing	<u>N75E</u>	<u>N74W</u>	_____	_____
Distance	<u>10 LKS</u>	<u>21 LKS</u>	_____	_____

Original Bearing Trees Found

Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1913 By JOHN CURO

Location filed COUNTY SURVEY RECORD BOOK "A" P. 592 604

Monument SET 2 1/2 x 48" GALV. I.P.

Evidence of Subsequent Corner Restoration

Year of search 1915 By _____

Twoprd order shows no survey

Bearing Trees, Reference Objects

Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

Bearing Trees, Reference Objects

_____	_____	_____	_____	_____
_____	_____	_____	_____	_____
_____	_____	_____	_____	_____
_____	_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed _____

Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____ By _____

Filed at _____ Date _____