


T. 138 R. 30 M. 5th Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_

NE 35 Corner common to sections 25, 26, 35, 36



EXISTING SURVEYS

Original Government Survey

Year surveyed 1865  
Original monument Post

Original Evidence Found

Year of search \_\_\_\_\_ by \_\_\_\_\_  
Monument found \_\_\_\_\_

Bearing Trees

Species	<u>Black Pine</u>	<u>Black Pine</u>	<u>Dead Bl. Pine</u>
Diameter	<u>12"</u>	<u>12"</u>	<u>13"</u>
Bearing	<u>N 35° E</u>	<u>N 31 1/2° W</u>	<u>S 63° W</u>
Distance	<u>127 links</u>	<u>54 links</u>	<u>84 links</u>

Original Bearing Trees Found

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1/1909 By J.W. Curo, LS 1428, Co. Surv.  
Location filed: Curo Book 85, page 287  
Monument: \_\_\_\_\_  
lists the GLO witnesses and states "all are gone."

Evidence of Subsequent Corner Restoration

Year of search 12/1914 By C.J. White, LS 1054, Asst. Eng.  
Location filed: Ditch Shelf 1, Book 21, page 11  
Monument: Iron pipe  
State Rural Highway Number 80, indicates corner is Iron pipe in concrete base, 177.8' W. of centerline at station 1826+49.

Bearing Trees, Reference Objects

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Bearing Trees, Reference Objects

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1926 By H.E. Palmer, MN/DOT  
Location filed: Certificate of Location  
Monument: Found capped iron pipe

Evidence of Subsequent Corner Restoration Found

Year of search 3/1980 By W.J. Spain  
Location filed: Certificate of Survey, #4448  
Monument: Found iron monument

1965, MN/DOT  
Certificate of Location  
Located 1.5" capped iron pipe in T.H. 371 survey

2/2002, D.S. Landecker, LS 17008  
Certificate of Survey for Bresnahan, #1558  
Indicates monument found.

9/1965, R.F. Schneider, LS 5740  
Survey Record Book D, page 456  
Found 1" Iron pipe and witnessed.  
Tele. Pole, N 71° W, 43.0'  
Power Pole, S 71° W, 52.9'  
5" N. Pine, S 17 1/2° W, 53.7'

8/2004, P.A. Trottier, LS 41002  
Certificate of Survey for Krammer, #2387  
Indicates a monument found at corner.

1970, D. Anderson, LS 3091  
Certificate of Location  
Used corner for preliminary survey work.

12/2004, P.A. Trottier, LS 41002  
Certificate of Survey for Kuschel, #2575  
Indicates a monument found at corner.

5/1978, A. Welle, LS 11873, MN/DOT  
Certificate of Location  
Found 3/4" pipe, lowered and set CIM, 4'+/-, N. of centerline.  
14" Balsam, South, 46.62' face tie, spike  
14" Norway Pine, SE, 129.53' face tie, spike  
Power Pole, SW, 53.29' copper nail and disc, up 2', SE side  
16" Norway Pine, SSW, 53.36' face tie, spike

6/2005, J.D. Walker, LS 16098, DNR  
Certificate of Survey for the PAUL BUNYAN TRAIL, #3115  
Indicates a MNDOT cast iron monument found at corner.

Subsequent Corner Restoration

Evidence of Subsequent Corner Restoration Found


Year surveyed 11/2018 By CCHD/SO  
 Location filed: #2018.026  
 Monument: Found a MNDOT cast iron monument  
 down 0.8', on centerline of 20th Street and the following.  
 24" Red Pine, S 22° W, 53.75'(1978)duplex nail, up 1.0', Eside  
 Power Pole, S 61° W, 55.32' 90d spike, up 0.6', N. side  
 9" Jack Pine, N 42° W, 70.61' 20d nail, up 2.1', E. side  
 Power Pole, N 25° E, 85.01' duplex nail, up 1.0', W. side

Year of search \_\_\_\_\_ By \_\_\_\_\_  
 Location filed: \_\_\_\_\_  
 Monument: \_\_\_\_\_

Index No. V 21

CASS COUNTY LAND CORNER RECORD

T. 138 R. 30 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
NE 35 Corner common to sections 25, 26, 35, 36



EXISTING SURVEYS

Original Government Survey  
 Year surveyed 1865  
 Original monument Post

Original Evidence Found  
 Year of search \_\_\_\_\_ By \_\_\_\_\_  
 Monument found \_\_\_\_\_

Bearing Trees  
 Species BL. PINE BL. PINE DEAD BL. PINE  
 Diameter 12" 12" 13"  
 Bearing N35E N31 1/2 W S63W  
 Distance 127 LKS. 54 LKS. 84 LKS.

Original Bearing Trees Found  
 Species \_\_\_\_\_  
 Diameter \_\_\_\_\_  
 Bearing \_\_\_\_\_  
 Distance \_\_\_\_\_

Subsequent Corner Restoration  
 Year surveyed 1965 By R. F. SCHNEIDER  
 Location filed COUNTY BOOK 'D' P. 456  
 Monument 1" IRON PIPE (NUT TIES)

Evidence of Subsequent Corner Restoration  
 Year of search 1924 By Minn. Hist Dept  
R/W map in Recorder's Office - Lathrop to Pine River  
iron pipe w/ cap.

Bearing Trees, Reference Objects  
 Species TELE. POLE POW. POLE N. PINE  
 Diameter \_\_\_\_\_ 5" \_\_\_\_\_  
 Bearing N71W S71W S17 1/2 W  
 Distance 43.0' 52.9' 53.7'

Bearing Trees, Reference Objects  
 \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_

V-21

Subsequent Corner Restoration  
 Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
 Location filed \_\_\_\_\_  
 Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found  
 Year of search \_\_\_\_\_ By \_\_\_\_\_  
CERTIFICATE - AL WELLS - Minn DOT - 1978  
Found 3/4" pipe (down 0.4') Set cast iron  
monument over found pipe. Ties: power  
pole SW 53.29'; 16" Norway Pine SSW 53.36';  
14" Balsam South 46.62'; 14" Norway SSE  
129.53'.  
Doc. #240557.  
FEB 2002 P LANDSCRER  
CERT of SUR shows mon found  
Aug. 2004 P. Trotter # 41002  
Cert. of Sur. Shows mon. found  
Dec. 2004 P. Trotter # 41002  
Cert. of Survey shows monument found

Remonumentation certificate prepared \_\_\_\_\_ By \_\_\_\_\_  
 Filed at \_\_\_\_\_ Date \_\_\_\_\_